



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 1337C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR O/S FENDER	BENT	985.00	935.00
1	REAR O/S FENDER AIR DUCT	SERVICEABLE	175.00	-
1	REAR O/S FENDER INNER TRIM BOARD	DEFORMED	455.00	273.00
1	REAR O/S FENDER INNERSHIELD	SERVICEABLE	105.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	95.00	95.00
1	REAR O/S TAIL-LAMP ASSY	CRACKED	772.00	659.40
1	REAR O/S TAIL-LAMP PANEL	BENT	205.00	205.00
1	REAR BUMPER	BUCKLED	655.00	601.00
1	REAR BUMPER LOWER GARNISH	SERVICEABLE	355.00	-
1	REAR O/S BUMPER SIDE RETAINER	CRACKED	65.00	65.00
1	REAR O/S REVERSE SENSOR	SERVICEABLE	205.00	-
1	REAR O/S DOOR ASSY	BENT	905.00	905.00
1	REAR O/S DOOR RUBBER	SERVICEABLE	155.00	-
1	REAR O/S DOOR INNER LOCK	TO REPAIR SEE LABOUR	287.00	-
1	FRONT O/S DOOR ASSY	BENT	985.00	985.00
1	FRONT O/S SHOCK ABSORBER	BENT	305.00	305.00
1	FRONT O/S LOWER ARM	DISTORTED	327.00	327.00
1	FRONT O/S KNUCKLE ARM	BENT	365.00	365.00
1	FRONT O/S KNUCKLE BEARING	NECESSARY	196.00	196.00
1	FRONT O/S HUB	BENT	355.00	355.00
1	REAR O/S SHOCK ABSORBER	BENT	287.00	287.00
1	REAR O/S HUB	BENT	325.00	325.00
1	REAR SENSOR AND LAMP CONTROL SWITCH	SERVICEABLE	487.00	-
2	REAR REVERSE SENSOR @\$265.00	SERVICEABLE	530.00	-
	LESS 10% DISCOUNT		-958.10	-688.34
			8,622.90	6,195.06
	<u>SPECIAL NETT ITEMS</u>			
2	FRONT & REAR O/S TYRE RIM @\$450.00 (SN)	FRONT DENTED	900.00	450.00

Report Ref No. CS/SMO23000325/Kqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
15	REAR BUMPER CLIP @\$2.00 (SN)	NECESSARY	30.00	30.00
			930.00	480.00
	LABOUR			
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, CUTTING & WELDING. INCLUSIVE OF THE REPAIR OF REAR O/S DOOR INNER LOCK.		1,800.00	1,000.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		1,600.00	1,000.00
	CHECK/RECONNECT WIRING.		45.00	20.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.		150.00	90.00
	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.		120.00	100.00
	REMOVE/REFIT FUEL TANK TO FACILITATE REPAIR.	NOT NECESSARY	100.00	-
	REMOVE/RENEW FRONT & REAR O/S UNDERCARRIAGES.		550.00	300.00
	CHECK AND REALIGN WHEEL ALIGNMENT.		80.00	60.00
			4,445.00	2,570.00
GRAND TOTAL			13,997.90	9,245.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,350.00

Report Ref No. CS/SMO23000325/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.