



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23000325/Kqy3m4 Date: 22/02/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 666T	Veh. Inspected	SJX 1337C
	Policy No.	D22TMHCVE000812	Coverage (\$)	0.00
	Claim No.	CMTD2300114/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	10/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	KNAFW411MA5191437	Colour	METALLIC SILVER
	Odometer	255872 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	YOKOHAMA	9 mm
	L/H Front Tyre	215/45 R17	YOKOHAMA	9 mm
	R/H Rear Tyre	215/45 R17	YOKOHAMA	9 mm
	L/H Rear Tyre	215/45 R17	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/01/2023	Inspection Date	11/01/2023
	Survey held at	5038 ANG MO KIO IND PARK 2, #01-405 (S569537)		
	Repairer	TRUST AUTOWORKS		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	