



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303675

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/06/2023
Reference CC6/CTI23000331/Kya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMY 3745D
Insured Veh. SLB 1081G
Claim No. SNM23D200295
Policy No. DMPCSNW00262352200
Accident Date 05/01/2023
Inspection Date 10/01/2023

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (8%) | 32.00 |
| Grand Total | 432.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|-----------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CC6/CTI23000331/Kya3q2 | |
| | | | Date: 12/06/2023 | |
| | | | Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLB 1081G | Veh. Inspected | SMY 3745D | |
| Policy No. | DMPCSNW00262352200 | Coverage (\$) | 0.00 | |
| Claim No. | SNM23D200295 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 10/01/2023 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA PRIUS (A) | c.c | 1798 | |
| Engine No. | HIDDEN | Year of Reg. | 2021 | |
| Chassis No. | JTDKB3FU503091585 | Colour | METALLIC SILVER | |
| Odometer | 148726 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | ARIVO | 8 mm | |
| L/H Front Tyre | 195/65 R15 | ARIVO | 8 mm | |
| R/H Rear Tyre | 195/65 R15 | CHAMPIRO | 8 mm | |
| L/H Rear Tyre | 195/65 R15 | CHAMPIRO | 8 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 05/01/2023 | Inspection Date | 10/01/2023 | |
| Survey held at | OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 2 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 3745D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | REAR BUMPER | BUCKLED | 458.00 | 458.00 |
| 1 | REAR BUMPER REINFORCEMENT | BUCKLED | 336.00 | 336.00 |
| 1 | REAR BUMPER LOWER LIP | DENTED | 486.00 | 486.00 |
| 1 | REAR TAILGATE (NPA) | TO REPAIR SEE LABOUR | - | - |
| | LESS 25% DISCOUNT | | -320.00 | -320.00 |
| | | | 960.00 | 960.00 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | REAR BUMPER CLIPS (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR BUMPER REVERSE SENSOR (SN) | SHORTED | 300.00 | 200.00 |
| | | | 350.00 | 250.00 |
| | <u>LABOUR</u> | | | |
| | LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR TAILGATE. | | 500.00 | 200.00 |
| | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID ,REAR BUMPER & ETC. | | 500.00 | 200.00 |
| | LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. | | 120.00 | 50.00 |
| | TO DIAGNOSIS FAULT CODE & RESET MEMORY . | NOT NECESSARY | 120.00 | - |
| | TO CHECK WIRING & ELECTRICAL SYSTEM. | NOT NECESSARY | 100.00 | - |
| | | | 1,340.00 | 450.00 |
| | GRAND TOTAL | | 2,650.00 | 1,660.00 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,300.00 |

Report Ref No. CC6/CTI23000331/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 3745D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 3745D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 3745D

RE-INSPECTION

