

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23000333/RWP3M4**Date:** 28/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00003032200

**Claimant Vehicle No :** SNJ623J **Insured Vehicle No :** SMT2860L

Date of Loss: 05/01/2023 Nature of Claim: TP Claim No: SNM23D200188/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNJ623J**

Make & Model: CITROEN C4, 1.2 FEEL L (A) Engine No: 10XVDW1902257

Reg. Date: 20/12/2022 (Man. Year: 2022) Chassis No: VR7BAHNSBNE025145

Colour: Black Odometer: 180 km

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,443.00	3,737.00	1,706.00	31.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,220.00	5,540.00	6,680.00	54.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,663.00</b>	<b>9,277.00</b>	<b>8,386.00</b>	<b>47.48</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,413.04</b>	<b>742.16</b>	<b>670.88</b>	<b>47.48</b>
<b>Nett Amount (S\$)</b>	<b>19,076.04</b>	<b>10,019.16</b>	<b>9,056.88</b>	<b>47.48</b>

**INSPECTION**

Date of Assignment: 21/02/2023

Date Inspected: 28/02/2023 Inspected At: Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)  
209 PANDAN GARDENS  
Singapore 609339

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Apr 2023)	
Parts:	N/A	CITROEN C4 1.2 FEEL L (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNJ623J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FILM TINT RH FRONT	Not Necessary	280.00 FS	*- FS
2	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
3	1		*FRONT DOOR RH A	Bent	1,210.00 FS	*1,210.00 FS
4	1		*DOOR HINGE RH SUP	Not Necessary	127.00 FS	*- FS
5	1		*DOOR HINGE RH INF	Not Necessary	127.00 FS	*- FS
6	1		*DOOR CHECKSTRAP	Not Necessary	100.00 FS	*- FS
7	1		*SEALING PANEL R	Necessary	94.00 FS	*94.00 FS
8	1		*DR WEATHERSTRIP	Necessary	190.00 FS	*190.00 FS
9	1		*MOULDING RH	Necessary	138.00 FS	*138.00 FS
10	1		*PROTECTEUR	Scratched	350.00 FS	*350.00 FS
11	1		*REAR DOOR RH AS	Bent	1,270.00 FS	*1,270.00 FS
12	1		*DOOR HINGE RH SUP	Not Necessary	70.00 FS	*- FS
13	1		*DOOR HINGE RH INF	Not Necessary	127.00 FS	*- FS
14	8		*PLUG	Necessary	88.00 FS	*88.00 FS
15	4		*ADHESIVE FILM DIAM 20	Necessary	48.00 FS	*48.00 FS
16	1		*FRT DOOR GLASS	Not Necessary	232.00 FS	*- FS
17	1		*WINDOW LIFTER RH	Not Necessary	456.00 FS	*- FS
18	1		*SIDE SILL SEAL	Not Necessary	127.00 FS	*- FS
19	1		*MANUF LABEL	Necessary	2.00 FS	*2.00 FS
20	1		*PROTECTEUR	Scratched	327.00 FS	*327.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,443.00	3,737.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRONT RH DOOR, REAR RH DOOR, REPAIR RH FENDER, REPAIR M PANEL, REPAIR ROCKER PANEL RH	New	6,080.00	1,900.00
2	SPRAY FRONT RH DOOR, REAR RH DOOR, RH M PANEL, FRONT BOTH DOOR TRIM LOWER, INNER ROCKER PANEL	New	3,300.00	1,100.00
3	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	380.00	380.00
4	CHECK ELECTRICAL AND WIRING	New	150.00	100.00
5	REMOVE AND REFIT DOOR TRIM RH FRONT	New	180.00	180.00
6	REMOVE AND REFIT REAR RH DOOR TRIM AND PANEL	New	160.00	160.00
7	SUPPLY SEALANT	New	120.00	100.00
8	ANTI RUST PROOFING	New	200.00	100.00
9	CALIBRATION ON POWER WINDOW INCLUDING TESTING	New	380.00	250.00
10	REPAIR RH SIDE ROCKER PANEL	New	720.00	720.00
11	RESPRAY RH SIDE ROCKER PANEL	New	550.00	550.00
<b>Gross Labour Cost (S\$)</b>			<b>12,220.00</b>	<b>5,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >