

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000335/KQP3Q2**Date:** 19/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNA00010792202		
Claimant Vehicle No :	SMK7247Y	Insured Vehicle No :	PC6610U		
Date of Loss:	01/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200050/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7247Y	Engine No:	2NRX444968
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	MHFZ28H3X00063304
Reg. Date:	23/04/2019 (Man. Year: 2019)	Odometer:	201156 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Arivo 9 mm	Rear Left Side:	Arivo 9 mm
Front Right Side:	Arivo 9 mm	Rear Right Side:	Arivo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,774.17	5,391.59	2,382.58	30.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,600.00	1,330.00	45.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,704.17	6,991.59	3,712.58	34.68
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	10,704.17	5,900.00	4,804.17	44.88

INSPECTION

Date of Assignment:	16/01/2023	
Date Inspected:	10/01/2023	Inspected At: BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047 Repairer:Ngs Motorsport Pte Ltd (HQ)
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7247Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BACK DOOR	Bent	1,185.00 FL	*1,121.80 FL
2	1		*GARNISH ,BACK DOOR (CHROME)	Warped / Cracked	211.58 FL	*211.58 FL
3	1		*STOPPER ,BACK DOOR LWR	Serviceable	49.81 FL	*- FL
4	2		*STOPPER ,BACK DOOR LWR RH/LH	Serviceable	99.62 FL	*- FL
5	1		*LOCK ,BACK DOOR ,W/COURTERSY LAMP SWITCH	Jammed	359.32 FL	*359.32 FL
6	1		*STICKER ASSY ,BACK DOOR	Repair	48.62 FL	*- FL
7	2		*STAY /DAMPER ,BACK DOOR UPP RH/LH	Serviceable	509.22 FL	*- FL
8	1		*GLASS ,BACK DOOR	Shattered	1,324.84 FL	*1,324.84 FL
9	1		*WEATHERSTRIP ,BACK DOOR	Distorted / Dented	219.98 FL	*219.98 FL
10	1		*MOULDING ,BACK DOOR ,OUTSIDE	Necessary	38.87 FL	*38.87 FL
11	2		*MOULDING ,BACK DOOR ,OUTSIDE RH/LH	Necessary	77.74 FL	*77.74 FL
12	1		*BOARD ASSY ,BACK DOOR TRIM	Buckled	189.57 FL	*189.57 FL
13	1		*TAILLAMP LH/RH	N/S Broken	707.72 FL	*353.86 FL
14	1		*BOOT LAMP LH/RH	N/S Broken	469.52 FL	*234.76 FL
15	1		*LAMP STEP ,STOP CENTER	Serviceable	189.42 FL	*- FL
16	2		*LICENSE LAMP LH/RH	Cracked	178.84 FL	*178.84 FL
17	1		*RR WIPER MOTOR	Serviceable	388.39 FL	*- FL
18	1		*RR WIPER ARM	Serviceable	73.96 FL	*- FL
19	1		*RR WIPER BLADE	Serviceable	65.80 FL	*- FL
20	1		*REAR BUMPER	Buckled / Dented	399.68 FL	*342.00 FL
21	2		*EXTENSION ,REAR BUMPER RH/LH	Serviceable	231.38 FL	*- FL
22	1		*EXTENSION ,REAR BUMPER CTR	Dented / Cut	188.13 FL	*188.13 FL
23	1		*PLATE ,REAR BUMPER LH	Serviceable	20.00 FL	*- FL
24	2		*SEAL ,REAR BUMPER RH/LH	Distorted	98.28 FL	*98.28 FL
25	2		*SUPPORT REAR BUMPER RH/LH	Distorted	158.44 FL	*158.44 FL
26	1		*RETAINER ,OUTSIDE RH/LH	N/S Distorted	162.78 FL	*81.39 FL
27	1		*SIDE RETAINER RH/LH	N/S Distorted	190.00 FL	*95.00 FL
28	1		*PANEL ,LOWER BACK OUTER	Bent	394.42 FL	*394.42 FL
29	1		*END PANEL LOWER BACK	Bent	632.88 FL	*608.10 FL
30	1		*COVER ,SLIDE DOOR CTR RAIL LH	Cracked	588.62 FL	*522.10 FL
31	4		*CUSHION /CLIPS ,REAR BUMPER	Necessary	147.52 FS	*60.00 FS
32	1		*BADGE ,BACK DOOR	Necessary	52.40 FS	*52.40 FS
33	1		*BACK DOOR NAME SIENTA	Necessary	52.40 FS	*52.40 FS
34	1		*BACK DOOR NAME G	Necessary	42.53 FS	*42.53 FS
35	1		*NO PLATE C/W CASING	Dented	50.00 FS	*45.00 FS
36	1		*SEALANT	Necessary	60.00 FS	*40.00 FS
37	1		*PARKING SENSOR	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,137.28	7,091.35
- List Item Discount on L Items 25.00/25.00% (S\$)	2,363.11	1,699.76
Total Parts (S\$)	7,774.17	5,391.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENTS /ATTACHMENTS .STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL INACCORDENCE WITH FACTORY SPECIFICATIONS .REPLACE /REPOSITION DAMAGED PARTS ,REFIT ALIGN INTO POSITION .REFIX ALL NECESSARY COMPONENTS /ATTACHMENTS	New	1,600.00	700.00
2	TO TRANSFER BACK DOOR & ALL MECHANISM & ETCS	New	100.00	60.00
3	TO REPLACE REAR WINDSCREEN GLASS	New	180.00	120.00
4	SPRAY PAINT ON REPLACE /REPAIR BODY PARTS	New	1,000.00	700.00
5	TO REMOVE/REFIT WIRE HARNESS ,ALL RELATED CONNECTOR ,CHECK PROPER FUNCTION	New	50.00	20.00
Gross Labour Cost (\$\$)			2,930.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >