

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000336/KQP3Q2**Date:** 16/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00257032100
Claimant Vehicle No :	SDZ456J	Insured Vehicle No :	SNB322U
Date of Loss:	10/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200236/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ456J	Engine No:	15E4E8AGL8200475
Make & Model:	M.G. HS, 1.5 T (A)	Chassis No:	LSJA24U91LN029558
Reg. Date:	29/10/2020 (Man. Year: 2020)	Odometer:	31984 km
Colour:	Metallic Red		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,326.50	2,326.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,160.00	1,520.00	56.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,006.50	3,486.50	1,520.00	30.36
+ GST 8.00/8.00% (S\$)	400.52	278.92	121.60	30.36
Nett Amount (S\$)	5,407.02	3,765.42	1,641.60	30.36

INSPECTION

Date of Assignment:	10/01/2023		
Date Inspected:	11/01/2023	Inspected At:	Toh Ah Swee Spray Painting Co. (HQ) 60 Jalan Lam Huat, #07-33/34 Carros Centre Singapore 737869
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts:	M1-SUV	M.G. HS 1.5 T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDZ456J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR (WCP)	Bent	1,500.00 F	*1,500.00 F
2	1		*LH FRONT DOOR GARNISH (WCP)	Dented	347.00 F	*347.00 F
3	1		*LH REAR DOOR GARNISH (WCP)	Dented	268.00 F	*268.00 F
						F=Franchise part.
					Sub Total (\$\$)	2,115.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	211.50
					Total Parts (\$\$)	2,326.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY PAINTING ON AFFECTED PART (PEARL RED)	New	1,200.00	600.00
2	TO REMOVE DAMAGED PARTS ,TO KNOCK OUT DENTS ,TO STRAIGHTEN,ADJUST CHECK RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS ,TO REPLACE AND ALIGN THE ABOVE PARTS	New	900.00	400.00
3	TO REMOVE AND REFIX MECHANISM }	New	250.00	60.00
4	TO CHECK WIRING FOR POWER WINDOW CENTRE LOCK }	New	180.00	0.00
5	TO COMPUTER RESET AFTER INSTALL PART	New	150.00	100.00
Gross Labour Cost (S\$)			2,680.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >