

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG23000342/UYA3Q2
Date: 09/06/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100486473
Claimant Vehicle No : SLE6894D **Insured Vehicle No :** SLG4610J
 Date of Loss: 04/01/2023 Nature of Claim: TP Claim No: 5873510427SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE6894D**
 Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGGH638110
 Reg. Date: 29/07/2016 (Man. Year: 2016) Chassis No: KNAFZ411MH5649048
 Colour: White Odometer: 94975 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,847.52	984.65	3,862.87	79.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	650.00	2,910.00	81.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,407.52	1,634.65	6,772.87	80.56
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	8,407.52	1,300.00	7,107.52	84.54
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
Nett Liability (S\$)		1,500.00		
Global Sum Settlement (S\$)		1,400.00		

INSPECTION

Date of Assignment: 10/01/2023
 Date Inspected: 10/01/2023 Inspected At: Zoom Autowerks Pte Ltd (HQ)
 130 Bedok Reservoir Road, Eunos Spring, #08-1339
 Singapore 470130
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP LH	Not Necessary	487.60 FL	*- FL
2	1		*REAR BUMPER	Deep Cut	858.00 FL	*688.00 FL
3	1		*REAR BUMPER INNER SPONGE	Not Necessary	145.50 FL	*- FL
4	1		*REAR BUMPER REFLECTOR (N/S)	Scratched	95.00 FL	*52.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	356.00 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER	Not Necessary	38.50 FL	*- FL
7	2		*REAR BUMPER PDC SENSORS	Not Necessary	373.00 FL	*- FL
8	1		*REAR BUMPER LOWER DIFFUSER	Grazed	298.50 FL	*298.50 FL
9	1		*REAR FENDER -LH	Not Necessary	889.60 FL	*- FL
10	1		*REAR WHEEL HUB WITH BEARING	Not Necessary	289.50 FL	*- FL
11	1		*REAR SHOCK ABSORBER	Not Necessary	221.60 FL	*- FL
12	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
13	1		*REAR TYRE	Not Necessary	400.00 FS	*- FS
14	1		*REAR WHEEL RIM -LH	Not Necessary	750.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,252.80	1,088.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	405.28	103.85
Total Parts (\$\$)	4,847.52	984.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECL UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	300.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
6	TO APPLY UNDERCOATING	New	100.00	0.00
7	PANEL BEATING	New	1,400.00	200.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	380.00
Gross Labour Cost (\$\$)			3,560.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >