

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CS6/AIS23000348/TCY3E2**Date:** 26/07/2023**REFERENCE**

Insured/Claimant:	HENG BOO CHYE	Policy No:	SP2001529616	
Date of Loss:	01/01/2023	Nature of Claim:	OD	Claim No: 202332004275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA8553H		
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Engine No:	27186030188639
Reg. Date:	07/04/2011 (Man. Year: 2010)	Chassis No:	WDD2120472A387296
Colour:	Black	Odometer:	233158 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	S\$96,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,353.00	489.50	863.50	63.82
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	830.00	600.00	230.00	27.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,218.00	1,124.50	1,093.50	49.30
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	2,218.00	524.50	1,693.50	76.35
+ GST 8.00/8.00% (\$\$)	177.44	41.96	135.48	76.35
Nett Amount (\$\$)	2,395.44	566.46	1,828.98	76.35

INSPECTION

Date of Assignment:	10/01/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	10/01/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2023)
Parts:	M1-COUPE	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA8553H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER (WCP)	Repair	785.00 F	*- F
2	1		*1 PC FRT GRILLE ASSY (WCP)	Cracked	445.00 F	*445.00 F
F=Franchise part.						
Sub Total (\$\$)					1,230.00	445.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					123.00	44.50
Total Parts (\$\$)					1,353.00	489.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT NUMBER PLATE (CRACKED)	35.00	35.00
Sub Total (\$\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE DAMAGE PARTS AND ATTACHMENTS. PANEL BEAT AND REPAIR RH HEADLAMP PANEL, INNER PANEL AND BONNET. REALIGN AND REPLACE FRT END DAMAGE BODY PARTS.	New	450.00	300.00
2	SPRAY PAINTING ON FRT BUMPER, FRT END TOP PANEL.	New	380.00	300.00
Gross Labour Cost (\$\$)			830.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >