

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS23000353/TVY3E2**Date:** 26/05/2023**REFERENCE**

Insured/Claimant: NIRMALJIT KAUR D/O BULWANT SINGH

Policy No: MPC22A00072301

Date of Loss: 07/01/2023

Nature of Claim: OD

Claim No: DMPC2300023H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJT7679Y**

Make & Model: SUZUKI SWIFT, 1.6 (M)

Engine No: M16A1483534

Reg. Date: 29/10/2009 (Man. Year: 2009)

Chassis No: JSAEZC31S00204811

Colour: Blue

Odometer: 266406 km

Engine Capacity: 1586 cc

Market Value/New Car Price: S\$70,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R16

Rear Tyre Size: 205/45 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,826.30	18,668.30	2,158.00	10.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	2,230.00	420.00	15.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,476.30	20,898.30	2,578.00	10.98
Approved Total (Overridden) (S\$)		16,700.00		
- Excess (S\$)	0.00	4,250.00	-4,250.00	
(S\$)	23,476.30	12,450.00	11,026.30	46.97
+ GST 8.00/8.00% (S\$)	1,878.10	996.00	882.10	46.97
Nett Amount (S\$)	25,354.40	13,446.00	11,908.40	46.97

INSPECTION

Date of Assignment: 11/01/2023 Present Location:

Yew Tee Automobile Tech Pte Ltd (Woodlands)

Date Inspected: 11/01/2023 Inspected At:

Yew Tee Automobile Tech Pte Ltd (Woodlands)
39 Woodlands Close #01-12, Mega@Woodlands
Singapore 737856

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2023)
Parts:	144	SUZUKI SWIFT 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT7679Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	450.00 F	*450.00 F
2	1		*FRONT BUMPER RETAINER LH (WCP)	Cracked	25.00 F	*25.00 F
3	1		*FRONT BUMPER RETAINER RH (WCP)	Distorted	25.00 F	*25.00 F
4	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	185.00 F	*185.00 F
5	1		*FRONT BUMPER FOG LAMP LH (WCP)	Cut	160.00 F	*160.00 F
6	1		*FRONT BUMPER FOG LAMP RH (WCP)	Missing	160.00 F	*160.00 F
7	1		*FRONT BUMPER FOG LAMP GARNISH LH (WCP)	Cut	95.00 F	*95.00 F
8	1		*FRONT BUMPER FOG LAMP GARNISH RH (WCP)	Missing	95.00 F	*95.00 F
9	1		*FRONT BUMPER LOWER BEAM (WCP)	Bent	148.00 F	*148.00 F
10	1		*FRONT BUMPER LOWER GRILLE (WCP)	Missing	153.00 F	*153.00 F
11	1		*FRONT GRILLE (WCP)	Cracked	164.00 F	*164.00 F
12	1		*FRONT GRILLE LOGO (WCP)	Necessary	48.00 F	*48.00 F
13	1		*BONNET (WCP)	Distorted	450.00 F	*450.00 F
14	1		*BONNET HINGES LH (WCP)	Bent	65.00 F	*65.00 F
15	1		*BONNET HINGES RH (WCP)	Bent	65.00 F	*65.00 F
16	1		*BONNET LOCK (WCP)	Bent	175.00 F	*175.00 F
17	1		*BONNET LOCK CABLE (WCP)	Distorted	145.00 F	*145.00 F
18	1		*FRONT HEADLAMP LH (WCP)	Cracked	330.00 F	*330.00 F
19	1		*FRONT HEADLAMP RH (WCP)	Cracked	330.00 F	*330.00 F
20	1		*FRONT HEADLAMP PANEL LH (WCP)	Bent	80.00 F	*80.00 F
21	1		*FRONT HEADLAMP PANEL RH (WCP)	Bent	80.00 F	*80.00 F
22	1		*FRONT HEADLAMP LOWER BRACKET LH (WCP)	Distorted	48.00 F	*48.00 F
23	1		*FRONT HEADLAMP LOWER BRACKET RH (WCP)	Missing	48.00 F	*48.00 F
24	1		*FRONT FENDER LH (WCP)	Bent	280.00 F	*280.00 F
25	1		*FRONT FENDER RH (WCP)	Bent	280.00 F	*280.00 F
26	1		*FRONT FENDER INNER SHIELD LH (WCP)	Torn	145.00 F	*145.00 F
27	1		*FRONT FENDER INNER SHIELD RH (WCP)	Torn	145.00 F	*145.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT FENDER INNER PANEL RH (WCP)	Repair	360.00 F	*- F
29	1		*FRONT FENDER WHEELHOUSE PANEL RH (WCP)	Repair	550.00 F	*- F
30	1		*FRONT DOOR RH (NPA)	Repair	0.00 F	*- F
31	1		*FRONT SUPPORT PANEL (WCP)	Bent	377.00 F	*377.00 F
32	1		*WASHER TANK (WCP)	Deformed	170.00 F	*170.00 F
33	1		*WASHER TANK MOTOR (WCP)	Deformed	153.00 F	*153.00 F
34	1		*WASHER TANK NECK FILLER (WCP)	Missing	90.00 F	*90.00 F
35	1		*FRONT INTERCOOLER (WCP)	Bent	850.00 F	*850.00 F
36	2		*FRONT INTERCOOLER PIPE (WCP)	Torn	310.00 F	*310.00 F
37	1		*AIR CON CONDENSER (WCP)	Bent	485.00 F	*485.00 F
38	2		*AIR CON CONDENSER SIDE COVER (WCP)	Deformed	110.00 F	*110.00 F
39	1		*AIR CON COMPRESSOR (WCP)	Not Necessary	630.00 F	*- F
40	1		*AIR CON SUCTION PIPE (WCP)	Not Necessary	120.00 F	*- F
41	1		*AIR CON RETURN PIPE (WCP)	Bent	160.00 F	*160.00 F
42	1		*AIR DISCHARGE PIPE (WCP)	Bent	150.00 F	*150.00 F
43	1		*RADIATOR (WCP)	Bent	700.00 F	*700.00 F
44	1		*RADIATOR LOWER CROSSMEMBER (WCP)	Bent	340.00 F	*340.00 F
45	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	55.00 F	*- F
46	1		*RADIATOR BOTTOM HOSE (WCP)	Not Necessary	65.00 F	*- F
47	1		*RADIATOR FAN COWLING (WCP)	Bent	156.00 F	*156.00 F
48	1		*RADIATOR FAN MOTOR (WCP)	Cut	360.00 F	*360.00 F
49	1		*RADIATOR FAN BLADE (WCP)	Jammed	105.00 F	*105.00 F
50	1		*FRONT CHASSIS MEMBER LH (NPA)	Not Necessary	0.00 F	*- F
51	1		*FRONT CHASSIS MEMBER RH (NPA)	Not Necessary	0.00 F	*- F
52	1		*FRONT EXHAUST PIPE (WCP)	Bent	860.00 F	*860.00 F
53	1		*FRONT EXHAUST PIPE HEAT SHIELD (WCP)	Bent	190.00 F	*190.00 F
54	1		*ENGINE OIL SUMP (WCP)	Cracked	310.00 F	*310.00 F
55	1		*ENGINE OIL FILTER HOUSING (WCP)	Distorted	230.00 F	*230.00 F
56	1		*ENGINE LOWER CROSSMEMBER (WCP)	Bent	700.00 F	*700.00 F
57	1		*ENGINE LOWER COVER (WCP)	Missing	210.00 F	*210.00 F
58	1		*FRONT LOWER ARM LH (WCP)	Bent	355.00 F	*355.00 F
59	1		*FRONT LOWER ARM RH (WCP)	Bent	355.00 F	*355.00 F
60	1		*FRONT KNUCKLE ARM LH (WCP)	Bent	382.00 F	*382.00 F
61	1		*FRONT KNUCKLE ARM RH (WCP)	Bent	382.00 F	*382.00 F
62	1		*FRONT SHOCK ABSORBER LH (WCP)	Bent	610.00 F	*610.00 F
63	1		*FRONT SHOCK ABSORBER RH (WCP)	Bent	610.00 F	*610.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*FRONT STABILIZER BAR LINK LH (WCP)	Bent	127.00 F	*127.00 F
65	1		*FRONT STABILIZER BAR LINK RH (WCP)	Bent	127.00 F	*127.00 F
66	1		*FLOOR UNDER PANEL (NPA)	Repair	0.00 F	*- F
67	1		*ROCKER PANEL LH (NPA)	Repair	0.00 F	*- F
68	1		*ROCKER PANEL GARNISH LH (WCP)	Cracked	750.00 F	*750.00 F
69	1		*ENGINE OIL (4L) (WCP)	Necessary	75.00 F	*75.00 F
70	1		*ENGINE OIL FILTER (WCP)	Bent	10.00 F	*10.00 F
71	1		*FRONT BUMPER CLIPS (SET) (WCP)	Necessary	30.00 F	*30.00 F
72	2		*FRONT FENDER INNER SHIELD CLIPS (SET) (WCP)	Necessary	50.00 F	*50.00 F
73	1		*FRONT NUMBER PLATE (WCP)	Missing	30.00 F	*30.00 F
74	1		*FRONT SPORTS RIM LH (WCP)	Bent	300.00 F	*300.00 F
75	1		*FRONT SPORTS RIM RH (WCP)	Dented	300.00 F	*300.00 F
76	1		*FRONT TYRES LH (70%)	Cut	250.00 F	*175.00 FS
77	1		*FRONT TYRES RH (70%)	Cut	250.00 F	*175.00 FS
Supplementary #1						
78	1		*ENGINE MOUNTING LEFT (WCP)	Bent	250.00 F	*250.00 F
79	1		*ENGINE MOUNTING RIGHT (WCP)	Bent	280.00 F	*280.00 F
80	1		*ENGINE MOUNTING REAR (WCP)	Bent	240.00 F	*240.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	18,933.00	17,003.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,893.30	1,665.30
Total Parts (S\$)	20,826.30	18,668.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	50.00	30.00
2	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,200.00	1,000.00
3	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,400.00	1,200.00
Gross Labour Cost (\$\$)			2,650.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >