

ASS. RECEBY: T. J. J. J.REF: CS/10523000353/10y3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. MPC22A00072301Claims No. DMPC2300023H/STSum Insured: _____ Excess: \$4250

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$70K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 55T 76799 Yr Regn: 2009 Apr. 1

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Suzuki Swift 1.6M C.C. 1586Colour: Blue A/C: Insured / Std / Nil / NASp. Reading: 266406 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 854122C 380020481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45K16R: L

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 7/1/2023 D.O.I. 11/1/23Survey held at Yew Tee WLDes. of Damages: Frt / Rear / O/S / N/S U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/5/23 Lump Sum \$16,700 confirmed by email (Red 6776.30, 28%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 23/5/23-typist

Report Format: MerimenLump Sum / TP: \$16,700Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : Off. Attend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

Yew Tee Automobile Tech Pte Ltd

39 Woodlands Close #01-12, Mega@Woodlands

Singapore 737856

Tel: 62562081 Email: info@yewteegroup.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC22A00072301	Date of Loss:	07/01/2023
Vehicle Reg. No.:	SJT7679Y	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NIRMALJIT KAUR D/O BULWANT SINGH		
Driver:	JASPAL SINGH PADDA S/O BALBIR SINGH		

Make/Model:	SUZUKI SWIFT, 1.6 (M)	Vehicle Reg. Date:	29/10/2009
Vehicle Colour:	BLUE		
Engine No:	M16A1483534	Chassis No:	JSAEZC31S00204811
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		

Present Location: YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)

COST OF CLAIMS

Parts	19,979.30
Miscellaneous Items	0.00
Labour	2,650.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	22,629.30
+ GST 8.00% (S\$)	1,810.34
Nett Amount (S\$)	24,439.64

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts: 144 SUZUKI SWIFT 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Yew Tee Automobile Tech Pte Ltd/SJT7679Y/10/01/2023 18:31
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	cur *450.00 F
2	1		*FRONT BUMPER RETAINER LH	0.00	0.00	? *25.00 F
3	1		*FRONT BUMPER RETAINER RH	0.00	0.00	dis *25.00 F
4	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	bt *185.00 F
5	1		*FRONT BUMPER FOG LAMP LH	0.00	0.00	cut *160.00 F
6	1		*FRONT BUMPER FOG LAMP RH	0.00	0.00	mis *160.00 F
7	1		*FRONT BUMPER FOG LAMP GARNISH LH	0.00	0.00	cut *95.00 F
8	1		*FRONT BUMPER FOG LAMP GARNISH RH	0.00	0.00	mis *95.00 F
9	1		*FRONT BUMPER LOWER BEAM	0.00	0.00	bt *148.00 F
10	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	mis *153.00 F
11	1		*FRONT GRILLE	0.00	0.00	cur *164.00 F
12	1		*FRONT GRILLE LOGO	0.00	0.00	new *48.00 F
13	1		*BONNET	0.00	0.00	dis *450.00 F
14	1		*BONNET HINGES LH	0.00	0.00	? *65.00 F
15	1		*BONNET HINGES RH	0.00	0.00	? *65.00 F
16	1		*BONNET LOCK	0.00	0.00	bt *175.00 F
17	1		*BONNET LOCK CABLE	0.00	0.00	? *145.00 F
18	1		*FRONT HEADLAMP LH	0.00	0.00	? *330.00 F
19	1		*FRONT HEADLAMP RH	0.00	0.00	cur *330.00 F
20	1		*FRONT HEADLAMP PANEL LH	0.00	0.00	? *80.00 F
21	1		*FRONT HEADLAMP PANEL RH	0.00	0.00	bt *80.00 F
22	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	? *48.00 F
23	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	mis *48.00 F
24	1		*FRONT FENDER LH	0.00	0.00	Rx *280.00 F
25	1		*FRONT FENDER RH	0.00	0.00	bt *280.00 F
26	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	in *145.00 F
27	1		*FRONT FENDER INNER SHIELD RH	0.00	0.00	in *145.00 F
28	1		*FRONT FENDER INNER PANEL RH	0.00	0.00	Rx *360.00 F
29	1		*FRONT FENDER WHEELHOUSE PANEL RH	0.00	0.00	Rx *550.00 F
30	1		*FRONT DOOR RH	0.00	0.00	Rx *-F
31	1		*FRONT SUPPORT PANEL	0.00	0.00	bt *377.00 F
32	1		*WASHER TANK	0.00	0.00	de *170.00 F
33	1		*WASHER TANK MOTOR	0.00	0.00	? *153.00 F
34	1		*WASHER TANK NECK FILLER	0.00	0.00	mis *90.00 F
35	1		*FRONT INTERCOOLER	0.00	0.00	bt *850.00 F
36	2		*FRONT INTERCOOLER PIPE	0.00	0.00	? *310.00 F
37	1		*AIR CON CONDENSER	0.00	0.00	bt *485.00 F
38	2		*AIR CON CONDENSER SIDE COVER	0.00	0.00	de *110.00 F
39	1		*AIR CON COMPRESSOR	0.00	0.00	? *630.00 F
40	1		*AIR CON SUCTION PIPE	0.00	0.00	? *120.00 F
41	1		*AIR CON RETURN PIPE	0.00	0.00	? *160.00 F
42	1		*AIR DISCHARGE PIPE	0.00	0.00	? *150.00 F
43	1		*RADIATOR	0.00	0.00	? *700.00 F
44	1		*RADIATOR LOWER CROSSMEMBER	0.00	0.00	bt *340.00 F
45	1		*RADIATOR TOP HOSE	0.00	0.00	? *55.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*RADIATOR BOTTOM HOSE	0.00	0.00	*65.00 F
47	1		*RADIATOR FAN COWLING	0.00	0.00	*156.00 F
48	1		*RADIATOR FAN MOTOR	0.00	0.00	*360.00 F
49	1		*RADIATOR FAN BLADE	0.00	0.00	*105.00 F
50	1		*FRONT CHASSIS MEMBER LH	0.00	0.00	*-F
51	1		*FRONT CHASSIS MEMBER RH	0.00	0.00	*-F
52	1		*FRONT EXHAUST PIPE	0.00	0.00	*860.00 F
53	1		*FRONT EXHAUST PIPE HEAT SHIELD	0.00	0.00	*190.00 F
54	1		*ENGINE OIL SUMP	0.00	0.00	*310.00 F
55	1		*ENGINE OIL FILTER HOUSING	0.00	0.00	*230.00 F
56	1		*ENGINE LOWER CROSSMEMBER	0.00	0.00	*700.00 F
57	1		*ENGINE LOWER COVER	0.00	0.00	*210.00 F
58	1		*FRONT LOWER ARM LH	0.00	0.00	*355.00 F
59	1		*FRONT LOWER ARM RH	0.00	0.00	*355.00 F
60	1		*FRONT KNUCKLE ARM LH	0.00	0.00	*382.00 F
61	1		*FRONT KNUCKLE ARM RH	0.00	0.00	*382.00 F
62	1		*FRONT SHOCK ABSORBER LH	0.00	0.00	*610.00 F
63	1		*FRONT SHOCK ABSORBER RH	0.00	0.00	*610.00 F
64	1		*FRONT STABILIZER BAR LINK LH	0.00	0.00	*127.00 F
65	1		*FRONT STABILIZER BAR LINK RH	0.00	0.00	*127.00 F
66	1		*FLOOR UNDER PANEL	0.00	0.00	*-F
67	1		*ROCKER PANEL LH	0.00	0.00	*-F
68	1		*ROCKER PANEL GARNISH LH	0.00	0.00	*750.00 F
69	1		*ENGINE OIL (4L)	0.00	0.00	*75.00 F
70	1		*ENGINE OIL FILTER	0.00	0.00	*10.00 F
71	1		*FRONT BUMPER CLIPS (SET)	0.00	0.00	*30.00 F
72	2		*FRONT FENDER INNER SHIELD CLIPS (SET)	0.00	0.00	*50.00 F
73	1		*FRONT NUMBER PLATE	0.00	0.00	*30.00 F
74	1		*FRONT SPORTS RIM LH	0.00	0.00	*300.00 F
75	1		*FRONT SPORTS RIM RH	0.00	0.00	*300.00 F
76	1		*FRONT TYRES LH	0.00	0.00	*250.00 F
77	1		*FRONT TYRES RH	0.00	0.00	*250.00 F

F=Franchise part.

Sub Total (\$\$)	18,163.00
+ Margin on L,N Items 10.00% (\$\$)	1,816.30
Total Parts (\$\$)	19,979.30

Yew Tee Automobile Tech Pte Ltd/SJT7679Y/10/01/2023 18:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New 30	50.00
2	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New 1600	1,200.00
3	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New 1200	1,400.00
Gross Labour Cost (\$\$)			2,650.00

Yew Tee Automobile Tech Pte Ltd/SJT7679Y/10/01/2023 18:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749/62563561
Not Authorized 11/1/23 @ 1615
Ex: 94250
Revert
L/S Resurvey after repair
tanpin @hkauto.com.
8 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: