



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBU 150R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RIM	NOT NECESSARY	486.00	-
1	FRONT FORK	SERVICEABLE	702.00	-
1	HEADLIGHT	* CHECK	486.00	-
1	HEADLIGHT STAY	* CHECK	178.00	-
1	FRONT LH COWLING	* CHECK	98.00	-
	LESS 10% DISCOUNT		-	-
			1,950.00	-
	<u>SPECIAL NETT ITEMS</u>			
1	STEERING CONE & BEARING (SN)	NOT NECESSARY	120.00	-
			120.00	-
	<u>LABOUR</u>			
	FRONT FORK ALIGNMENT.		220.00	80.00
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	FRAME ALIGNMENT.	NOT NECESSARY	200.00	-
	WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS.		350.00	150.00
			890.00	230.00
	GRAND TOTAL		2,960.00	230.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$685.80 NETT)			230.00

Report Ref No. CS/LIP23000355/Uvy3m4

MARKET VALUE: \$15,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$10,373.00=NETT VALUE: \$4,627.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.