



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 7108C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	80.00	20.00
1	FRONT AND REAR NUMBER PLATE (SN)	SCRATCHED	200.00	80.00
1	REAR BUMPER (SN)	DEFORMED	1,503.00	1,503.00
1	BUMPER SKIRT (SN)	NOT NECESSARY	486.00	-
1	SET BRACKET (SN)	NOT NECESSARY	210.00	-
1	BUMPER BRACKET (SN)	NECESSARY	709.00	709.00
1	SENSOR SUPPORT (SN)	NOT NECESSARY	243.00	-
1	BRACKET SET LAT (SN)	NECESSARY	210.00	210.00
1	TLGT EXT PANEL (SN)	TO REPAIR SEE LABOUR	523.00	-
1	FRONT BUMPER (SN)	CRACKED	1,589.00	1,589.00
1	GUARD GRILLE INFERIEUR (SN)	CRACKED	469.00	469.00
1	BMPR RUBBR BOOT (SN)	NECESSARY	303.00	303.00
1	BUMPER MOULDING (SN)	NOT NECESSARY	344.00	-
1	BUMPER MOULDING (SN)	NOT NECESSARY	227.00	-
1	BUMPER MOULDING (SN)	NOT NECESSARY	261.00	-
1	SET ABSORBERS (SN)	NOT NECESSARY	124.00	-
1	PLUG LH (SN)	NOT NECESSARY	145.00	-
1	BUMPER BRACKET (SN)	NOT NECESSARY	679.00	-
1	FOG HEADLIGHT (SN)	NOT NECESSARY	199.00	-
1	BUMPER BRACKET (SN)	NECESSARY	423.00	423.00
1	HEADLIGHT ASSY LH (SN) (ADDITIONAL)	SCRATCHED	1,063.00	1,063.00
1	BUMPER BRACKET (SN) (ADDITIONAL)	NECESSARY	265.00	265.00
1	BUMPER BRACKET (SN) (ADDITIONAL)	NECESSARY	491.00	491.00
1	TAILGATE (SN) (ADDITIONAL)	CRACKED	2,988.00	2,988.00
1	BADGE (SN) (ADDITIONAL)	NECESSARY	91.00	91.00
1	BADGE (SN) (ADDITIONAL)	NECESSARY	114.00	114.00
			13,939.00	10,318.00

Report Ref No. CS/AWA23000365/Rvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	RENEW REAR BUMPER, REAR LOWER TAILGATE COVER, REPAIR REAR TAILGATE RENEW FRONT BUMPER. INCLUSIVE OF THE REPAIR OF TLGT EXT PANEL.		4,560.00	2,280.00
	REMOVE AND REFIT SENSOR.		100.00	60.00
	SPRAY FRONT BUMPER, REAR BUMPER,REAR TAILGATE TRIM, REAR TAILGATE REAR END PANEL, SPRAY FRONT BOTH FENDER, REAR BOTH FENDER.		4,950.00	1,650.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		380.00	380.00
	CHECK WIRING AND ELECTRICAL COMPONENT.		100.00	100.00
	ANTI RUST PROOFING.		150.00	100.00
	REMOVE AND REINSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST (ADDITIONAL).		380.00	380.00
	SUPPLY REAR WINDSCREEN GLASS SEALANT (ADDITIONAL).		80.00	80.00
	REPLACE TAILGATE (ADDITIONAL).		760.00	760.00
	RESPRAY TAILGATE (ADDITIONAL).		550.00	550.00
			12,010.00	6,340.00
	GRAND TOTAL		25,949.00	16,658.00
RECOMMENDED COST OF REPAIRS				16,658.00

Report Ref No. CS/AWA23000365/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.