



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. TRB 7376X (XE 5102X)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER FRAME (SN)	BENT	4,800.00	3,800.00
2	REAR NUMBER PLATE LAMP @\$60.00 (SN)	CRACKED	120.00	120.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
2	REAR REFLECTOR @\$25.00 (SN)	NOT NECESSARY	50.00	-
1	50KM/H STICKER (SN)	NOT NECESSARY	15.00	-
1	REFLECTIVE STICKER (SN)	NOT NECESSARY	50.00	-
			5,065.00	3,920.00
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	500.00
	SPRAY PAINTING.		800.00	450.00
	WIRING.		50.00	30.00
	TO APPLY TUFF COAT.		150.00	100.00
			1,800.00	1,080.00
GRAND TOTAL			6,865.00	5,000.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/AWA23000370/Aqy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.