



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 2541E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH REAR SLIDING DOOR (WCP)	BENT	950.00	950.00
1	RH REAR SLIDING DOOR LOWER HINGE ROLLER (WCP)	DISTORTED	120.00	120.00
1	RH REAR WHEEL RIM 14" (WCP)	DENTED	285.00	180.00
1	RH REAR WHEEL HUB CAP (WCP)	DENTED	145.00	145.00
1	RH REAR WHEEL BEARING (WCP)	BENT	120.00	120.00
	COST PLUS 15%		243.00	227.25
			1,863.00	1,742.25
<u>LABOUR</u>				
	TO REMOVE DAMAGED PARTS, TO JACK OUT RH REAR FENDER, TO REWELD, RESHAPE AND REPAIR RH REAR FENDER AND INNER PANEL, TO REMOVE AND REFIT RH REAR SLIDING DOOR, DOOR TRIM, LOCK, WINDOW, TO REPLACE DAMAGED PARTS AND ADJUST BODY PANEL ALIGNMENT.		580.00	450.00
	TO REMOVE AND CHECK RH REAR SUSPENSION SYSTEM AND REPLACE DAMAGED PARTS.		120.00	50.00
	TO PERFORM COMPUTERISED WHEEL ALIGNMENT.		60.00	60.00
	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRNG SYSTEM AND CHECK FOR FULL FUNCTIONALITY.		50.00	15.00
	TO APPLY ANTI-CORROSION TUFF-KOTE.		80.00	30.00
			890.00	605.00
GRAND TOTAL			2,753.00	2,347.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CS/GAI23000375/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.