LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III23000377/TWY3E2

01/02/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447 02

Claimant Vehicle EW3993J Insured Vehicle No: SLH3063P

No:

06/01/2023 Nature of Claim: ΤP Claim No: MFL2023D0000654 Date of Loss:

DESCRIPTION & IDENTIFICATION OF VEHICLE

EW3993J Reg No:

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) **Engine No:** 2AZF180664 Reg. Date: 21/08/2008 (Man. Year: 2008) Chassis No: ACR500075012 Colour: White Odometer: 265105 km

Engine Capacity: 2362 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 215/55 R17 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Nett Amount (S\$)		0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/01/2023

Toh Painting (HQ)

BLK 3 WOODLANDS ROAD 391C & 391G YEW TEE Date Inspected: 11/01/2023 Inspected At: IND ESTATE

Singapore 677966

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Feb 2023)

Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EW3993J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >