

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG123000380/UQY3Q2**Date:** 30/01/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** GBF996X **Insured Vehicle No :** GBK4980M

Date of Loss: 05/01/2023 Nature of Claim: TP Claim No: GBF996X230105

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF996X**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 263A50007592354

Reg. Date: 20/06/2016 (Man. Year: 2016) Chassis No: ZFA26300006C22617

Colour: White Odometer: 161890 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16

Front Left Side: Lassa 7 mm Rear Left Side: Lassa 7 mm

Front Right Side: Lassa 7 mm Rear Right Side: Lassa 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,545.00	4,256.93	2,288.07	34.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,000.00	500.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,045.00</b>	<b>5,256.93</b>	<b>2,788.07</b>	<b>34.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,045.00</b>	<b>4,200.00</b>	<b>3,845.00</b>	<b>47.79</b>

INSPECTION

Date of Assignment: 11/01/2023

Date Inspected: 11/01/2023 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)  
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @  
KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Jan 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF996X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Cracked	1,245.50 F	*864.07 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
3	1		*FRONT BUMPER SPONGE	Torn	117.60 F	*117.60 FL
4	1		*SET FRONT BUMPER SPONGE CLIPS	Not Necessary	50.00 FS	*- FS
5	1		*FRONT BUMPER LOWER GRILLE	Torn	685.00 F	*341.00 FL
6	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	65.00 FS	*- FS
7	1		*FRONT NUMBER PLATE & BASE	Serviceable	48.00 FS	*- FS
8	1		*FRONT NUMBER PLATE GARNISH	Deformed	387.00 F	*105.00 FL
9	1		*FRONT GRILLE	Cut	845.00 F	*317.80 FL
10	1		*FRONT GRILLE FIAT LOGO MOTIF	Cracked	142.10 F	*142.10 FL
11	2		*FRONT HEAD LAMP	Holder Cracked	1,724.80 F	*1,724.80 FL
12	1		*FRONT BONNET	Buckled	1,170.00 F	*1,067.55 FL
					<hr/>	
					Sub Total (\$\$)	6,545.00 4,729.92
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 472.99
					<hr/>	
					Total Parts (\$\$)	6,545.00 4,256.93
					<hr/>	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECL ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	450.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	500.00
4	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	40.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,500.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >