

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref	: CS3/ASM23000382/Tvp3m4	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date	e: 17/01/2023	
	ATTN: CHONG AR	NOLD	Coo	de: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 4509H	Veh. Inspected	FBR 718U	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S3M04HKT	Excess (\$)	0.00	
	Assign From	CHONG ARNOLD	Assign Date	11/01/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA ADV150	c.c	149	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	MH1KF6115KK007822	Colour	RED	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	110/80R14	MICHELIN	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	130/70R13	MICHELIN	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSBODY.	STAINED DAMAGES AT THE FF	RONT PORTION AND O	/S	
5. General Information					
	Accident Date	04/01/2023	Inspect Date / Time	12/01/2023 ( 04:15 PM )	
	Survey held at	BIKE DYNAMIC CENTRE			
	BLK 6 DEFU LANE 10 #01-55 SINGAPORE 539187				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			

Report Ref No. CS3/ASM23000382/Tvp3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser