

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000388/P3Q2**Date:** 20/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00019062200		
Claimant Vehicle No :	SLS7143H	Insured Vehicle No :	SJR9707Y		
Date of Loss:	10/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200239/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS7143H	Engine No:	1NZD109014
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603029056
Reg. Date:	17/11/2008 (Man. Year: 2008)	Odometer:	171747 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,527.00	3,700.50	826.50	18.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,420.00	540.00	27.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,487.00	5,120.50	1,366.50	21.07
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	6,487.00	4,000.00	2,487.00	38.34
+ GST 8.00/8.00% (\$\$)	518.96	320.00	198.96	38.34
Nett Amount (\$\$)	7,005.96	4,320.00	2,685.96	38.34

INSPECTION

Date of Assignment:	10/01/2023		
Date Inspected:	17/01/2023	Inspected At:	SME Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15 Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2023)
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS7143H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented / Bent	1,195.50 FL	*1,195.50 FL
2	1		*REAR BOOT LOGO	Not Necessary	75.00 FL	*- FL
3	1		*REAR BOOT LOCK	Twisted	395.00 FL	*395.00 FL
4	1		*REAR BOOT INNER RUBBER	Not Necessary	220.80 FL	*- FL
5	1		*REAR BOOT OUTER CHROME	Not Necessary	285.50 FL	*- FL
6	1		*REAR BUMPER	Deformed	1,650.70 FL	*1,250.00 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
8	2		*REAR BUMPER RETAINER	Bent	170.60 FL	*170.60 FL
9	1		*REAR END PANEL	Dented / Bent	625.80 FL	*625.80 FL
10	1		*REAR END PANEL TOP TRIM	Twisted	195.70 FL	*195.70 FL
11	2		*TAIL LAMP	Cracked	731.40 FL	*731.40 FL
12	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
13	1		*REAR BOOT SEALANT	Not Necessary	40.00 FS	*- FS
14	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,926.00	4,854.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,399.00	1,153.50
Total Parts (S\$)	4,527.00	3,700.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX REAR SENSOR	New	80.00	50.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY	New	100.00	60.00
4	TRANSFER REAR BOOT COMPONENTS	New	100.00	60.00
5	CAVITY PROTECTION ON AFFECTED AREAS	New	100.00	30.00
6	LABOUR CHARGE	New	750.00	600.00
7	SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (S\$)			1,960.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >