

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000390/UVP3Q2**Date:** 01/02/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00228662201

**Claimant Vehicle
No :** GBK6500C**Insured
Vehicle No :** SFV91A

Date of Loss: 04/01/2023

Nature of Claim: TP

Claim
No: SNM23D200065/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBK6500C**Make & Model: MERCEDES-BENZ GLC 250, 2.0 COUPE AMG
(A)

Engine No: 225A20006969910

Reg. Date: 12/10/2020 (Man. Year: 2020)

Chassis No: ZFA22500006S03436

Colour: White

Odometer: 64672 km

Engine Capacity: 1248 cc

Market Value/New Car
Price: N/ASum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,267.30	7,871.48	4,395.82	35.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	2,420.00	1,520.00	38.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,207.30	10,291.48	5,915.82	36.50
Approved Total (Overridden) (S\$)		8,200.00		
Nett Amount (S\$)	16,207.30	8,200.00	8,007.30	49.41

INSPECTION

Date of Assignment: 10/01/2023

Date Inspected: 11/01/2023 Inspected At:

Liu's Brother Auto Engineering Workshop (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Jan 2023)	
Parts:	N/A	MERCEDES-BENZ GLC 250 2.0 COUPE AMG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK6500C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAILGATE	Badly Dented	1,895.90 F	*1,895.90 FL
2	1		*REAR RH TAILGATE LOCK TOP	Not Necessary	189.30 F	*- FL
3	1		*REAR RH TAILGATE LOCK BOTTOM	Damaged	192.90 F	*192.90 FL
4	1		*REAR RH TAILGATE WEATHERSTRIP	Twisted	297.00 F	*297.00 FL
5	1		*REAR RH TAILGATE INNER TRIM BOARD	Not Necessary	364.90 F	*- FL
6	1		*SET REAR RH TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	127.20 F	*- FL
7	2		*REAR RH TAILGATE FIAT LOGO EMBLEM	Not Necessary	175.60 F	*- FL
8	3		*REAR RH TAILGATE PROFESSIONAL EMBLEM	Necessary (1 PCS ONLY)	490.50 F	*163.50 FL
9	1		*REAR RH TAILGATE 4 PAX STICKER	Necessary	15.00 FS	*10.00 FS
10	1		*REAR RH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
11	1		*REAR LH TAILGATE	Badly Dented	2,156.30 F	*2,156.30 FL
12	1		*REAR LH TAILGATE WEATHERSTRIP	Twisted	344.50 F	*344.50 FL
13	1		*REAR LH TAILGATE LOCK	Twisted / Jammed	331.00 F	*331.00 FL
14	1		*REAR LH TAILGATE FLORINO EMBLEM	Necessary	119.60 F	*119.60 FL
15	1		*REAR LH TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
16	1		*REAR LH TAILGATE NUMBER PLATE & BASE	Not Necessary	48.00 FS	*- FS
17	1		*REAR LH TAILGATE INNER TRIM BOARD	Not Necessary	384.90 F	*- FL
18	1		*SET REAR LH TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	164.50 F	*- FL
19	1		*REAR LH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
20	1		*REAR BUMPER	Distorted	745.00 F	*745.00 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
22	1		*REAR BUMPER RETAINER	Broken	117.00 F	*117.00 FL
23	1		*SET REAR BUMPER SPONGE CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
25	1		*REAR FLOOR PANEL GARNISH	Deformed	1,379.80 F	*366.10 FL
26	1		*REAR END PANEL OUTER	Badly Dented	430.00 F	*430.00 FL
27	1		*REAR END PANEL INNER	Badly Dented	295.00 F	*295.00 FL
28	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
29	2		*REAR TAIL LAMP	Cracked	853.40 F	*853.40 FL
30	1		*REAR SPARE TYRE CARRIER	Not Necessary	590.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,267.30	8,707.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	835.72
Total Parts (\$\$)	12,267.30	7,871.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REPLACE REAR REVERSE SENSOR	New	120.00	50.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	100.00	20.00
3	REMOVE AND REFIX REAR RH & LH TAILGATE COMPONENTS & WIPER MECHANISM	New	160.00	120.00
4	REMOVE AND REFIX 2 TAILGATE WINDSCREEN GLASS	New	240.00	200.00
5	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,800.00	1,100.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,400.00	850.00
7	TO APPLY RUST PROOFING ,RESEAL TUFF COATING TREATMENT ON ACCIDENT AREA	New	120.00	80.00
Gross Labour Cost (S\$)			3,940.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >