

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23000395/RQP3E2**Date:** 07/07/2023**REFERENCE**

Insured/Claimant: COUDRAY BOOKER MARIE EMMANUELLE LUCIE

Policy No: 1800152122

Date of Loss: 07/01/2023

Nature of Claim: OD

Claim No: 4876428375SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDB5957Z**

Make & Model: AUDI A8 L, 3.0 TFSI QU (A)

Engine No: CZS016956

Reg. Date: 31/12/2018 (Man. Year: 2018)

Chassis No: WAUZZZF82KN006271

Colour: Black

Odometer: 30486 km

Engine Capacity: 2995 cc

Market Value/New Car Price: S\$240,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/40 R20

Rear Tyre Size: 265/40 R20

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,792.00	29,758.08	18,033.92	37.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,302.00	4,652.00	2,650.00	36.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,094.00	34,410.08	20,683.92	37.54
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	54,394.00	33,710.08	20,683.92	38.03
+ GST 8.00/8.00% (S\$)	4,351.52	2,696.81	1,654.71	38.03
Nett Amount (S\$)	58,745.52	36,406.89	22,338.63	38.03

INSPECTION

Date of Assignment: 13/01/2023

Date Inspected: 11/01/2023 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,985.00 FS	*3,188.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	570.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Torn	456.00 FS	*364.40 FS
4	1		*FRONT BUMPER COVER - CENTER	Not Necessary	77.00 FS	*- FS
5	2		*FRONT BUMPER COVER - LH / RH	Not Necessary	176.00 FS	*- FS
6	1		*FRONT BUMPER BRACKET - LH / RH	Cracked	260.00 FS	*208.00 FS
7	1		*FRONT BUMPER CHROME TRIM - LH / RH	N/S Cracked / O/S Not Necessary	450.00 FS	*180.00 FS
8	1		*FRONT BUMPER TRIM CAP - LH	Cracked	18.00 FS	*13.84 FS
9	2		*FRONT BUMPER END CAP - LH / RH	Not Necessary	138.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Scratched/O/S Not Necessary	1,404.00 FS	*561.60 FS
11	1		*FRONT BUMPER OUTER TRIM - LH REAR UPPER	Not Necessary	260.00 FS	*- FS
12	2		*FRONT BUMPER OUTER TRIM - LH / RH LOWER	Not Necessary	520.00 FS	*- FS
13	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	310.00 FS	*247.60 FS
14	1		*FRONT BUMPER SPOILER	Cracked	349.00 FS	*279.20 FS
15	1		*FRONT BUMPER LOWER COVER BRACKET	Not Necessary	94.00 FS	*- FS
16	1		*RADIATOR GRILLE	Cracked	2,631.00 FS	*2,104.80 FS
17	1		*QUATTRO INSCRIPTION	Not Necessary	118.00 FS	*- FS
18	1		*RADIATOR GRILLE COVER	Not Necessary	74.00 FS	*- FS
19	1		*RADIATOR GRILLE COVER CAP	Not Necessary	149.00 FS	*- FS
20	1		*RADIATOR GRILLE BRACKET	Not Necessary	56.00 FS	*- FS
21	2		*RADIATOR GRILLE END CAP - LH / RH	Not Necessary	54.00 FS	*- FS
22	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	209.00 FS	*- FS
23	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	158.00 FS	*- FS
24	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	120.00 FS	*- FS
25	1		*FRONT LICENCE PLATE HOLDER	Not Necessary	972.00 FS	*- FS
26	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	72.00 FS	*- FS
27	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	149.00 FS	*- FS
28	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,412.00 FS	*- FS
29	1		*FRONT BUMPER CROSS MEMBER	Not Necessary	430.00 FS	*- FS
30	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	71.00 FS	*56.56 FS
31	1		*FRONT REBOUND STRAP	Not Necessary	94.00 FS	*- FS
32	1		*FRONT BUMPER BRACKET	Cracked	36.00 FS	*28.24 FS
33	1		*FRONT BUMPER TOP COVER	Cracked	236.00 FS	*188.40 FS
34	1		*FRONT BUMPER TOP COVER CAP	Not Necessary	41.00 FS	*- FS
35	1		*AIR CONDITIONER STICKER	Necessary	24.00 FS	*18.56 FS
36	1		*CAUTION SIGN STICKER	Necessary	17.00 FS	*13.28 FS
37	1		*HORN HIGH TONE - RH	Not Necessary	165.00 FS	*- FS
38	1		*HORN BRACKET - UPPER	Not Necessary	27.00 FS	*- FS
39	1		*HORN BRACKET - LOWER	Not Necessary	56.00 FS	*- FS
40	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	598.00 FS	*- FS
41	1		*FRONT PARKING AID SENSOR - OUTER (2PCS)	Cracked (1Pc Only)	598.00 FS	*239.20 FS
42	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	598.00 FS	*- FS
43	4		*FRONT PARKING AID SEAL RING	Necessary	11.00 FS	*8.32 FS
44	1		*SET FRONT BUMPER WIRING	Cut	756.00 FS	*604.40 FS
45	1		*FRONT FENDER - LH	Torn	3,088.00 FS	*2,470.40 FS
46	1		*FRONT FENDER BRACKET - LH FRONT	Cracked	100.00 FS	*79.28 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT FENDER BRACKET - LH CENTRE	Not Necessary	74.00 FS	*- FS
48	1		*FRONT FENDER BRACKET - LH UPPER	Not Necessary	35.00 FS	*- FS
49	1		*FRONT FENDER BRACKET - LH UPPER	Cracked	54.00 FS	*42.96 FS
50	1		*FRONT FENDER BRACKET - LH LOWER	Not Necessary	42.00 FS	*- FS
51	1		*FRONT FENDER BRACKET - LH REAR	Not Necessary	74.00 FS	*- FS
52	1		*FRONT FENDER BRACE - LH INNER	Cut	642.00 FS	*513.20 FS
53	1		*FRONT FENDER BRACE - LH OUTER	Cut	180.00 FS	*143.60 FS
54	1		*FRONT FENDER CONNECTING PIECE - LH	Cracked	215.00 FS	*171.60 FS
55	1		*FRONT FENDER RETAINING BRACKET - LH	Cracked	22.00 FS	*17.20 FS
56	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
57	1		*FRONT WHEEL HOUSING LINER - LH	Torn	495.00 FS	*395.60 FS
58	1		*FRONT WHEEL SPOILER - LH	Cracked	112.00 FS	*89.20 FS
59	1		*FRONT WHEEL SPOILER STONE CHIP GUARD - LH	Not Necessary	60.00 FS	*- FS
60	1		*FRONT FENDER CHROME LINING - LH	Necessary	190.00 FS	*151.60 FS
61	1		*HEADLIGHT - LH	Cracked	14,751.00 FS	*11,800.80 FS
62	2		*LIFT CYLINDER - LH / RH	Not Necessary	630.00 FS	*- FS
63	1		*LIFT CYLINDER HOSE	Not Necessary	104.00 FS	*- FS
64	1		*LIFT CYLINDER PIPE	Not Necessary	72.00 FS	*- FS
65	1		*LIFT CYLINDER WASH WATER RESERVOIR	Not Necessary	476.00 FS	*- FS
66	1		*FRONT ALUMINIUM RIM	Scratched	3,338.00 FS	*2,670.40 FS
67	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*3.04 FS
68	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
69	1		*SUNDRIES	Necessary	500.00 FS	*120.24 FS
70	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Cracked	551.00 FS	*440.40 FS
71	1		*FRONT BUMPER REINFORCEMENT BRACKET - RH (Supplementary)	Cracked	36.00 FS	*28.24 FS
72	2		*FRONT WHEEL SPOILER - RH (Supplementary)	Cracked	112.00 FS	*89.20 FS
73	1		*FRT FENDER TOP COVER - LH (Supplementary)	Scratched	42.00 FS	*33.28 FS
74	1		*WIRE CONNECTOR - 14PIN BROWN (Supplementary)	Necessary	35.00 FS	*27.68 FS
75	1		*WIRE CONNECTOR - 14PIN BLACK (Supplementary)	Necessary	30.00 FS	*23.60 FS
76	1		*ADAPTER CABLE LOOM (Supplementary)	Cracked	464.00 FS	*371.20 FS
77	1		*CORRUGATED PIPE (Supplementary)	Cut	97.00 FS	*77.28 FS
78	1		*CHARGE AIR COOLER AIR GUIDE - LH (Supplementary)	Cracked	81.00 FS	*64.08 FS
79	1		*CHARGE AIR COOLER - LH (Supplementary)	Bent	1,962.00 FS	*1,569.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 47,792.00 29,758.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	300.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	1,200.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,200.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER 360 CAMERA, DISTANCE REGULATION AND RADAR SENSOR	New	480.00	480.00
6	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	320.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO DISMANTLE AND RENEW LHS CHARGE AIR COOLER (Supplementary)	New	480.00	480.00
Gross Labour Cost (\$)			7,302.00	4,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >