

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG23000410/UPA3Q2  
**Date:** 26/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100411044
<b>Claimant Vehicle No :</b>	SMJ4139B	<b>Insured Vehicle No :</b>	SGA8618C
Date of Loss:	11/01/2023	Nature of Claim:	TP
		Claim No:	0153641902SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMJ4139B</b>	Engine No:	G3LCJP139273
Make & Model:	KIA STONIC, 998cc DCT (A)	Chassis No:	KNAD6811VK6243225
Reg. Date:	04/03/2019 (Man. Year: 2018)	Odometer:	27236 km
Colour:	Silver		
Engine Capacity:	998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,882.35	5,962.13	13,920.22	70.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,920.00	2,560.00	2,360.00	47.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,802.35</b>	<b>8,522.13</b>	<b>16,280.22</b>	<b>65.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>24,802.35</b>	<b>6,800.00</b>	<b>18,002.35</b>	<b>72.58</b>
<b>+ Loss of Use (8.0 x S\$60.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		26.75		
<b>Nett Liability (S\$)</b>		<b>7,306.75</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,300.00</b>		

**INSPECTION**

Date of Assignment:	12/01/2023	Inspected At:	SPEEDWERKZ PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6 #01-73, Singapore 417883
Date Inspected:	12/01/2023		
Estimated Period of Repair:	7.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Badly Dented	1,366.00 FL	*1,366.00 FL
2	1		*REAR TAIL GATE EMBLEM (TGDI)	Necessary	78.00 FL	*48.00 FL
3	1		*REAR TAIL GATE EMBLEM (STONIC)	Necessary	62.50 FL	*52.00 FL
4	1		*REAR TAIL GATE LOGO	Necessary	65.00 FL	*65.00 FL
5	2		*REAR TAIL GATE LAMP	Not Necessary	938.60 FL	*- FL
6	1		*REAR TAIL GATE LOCK	Twisted	321.70 FL	*106.00 FL
7	1		*REAR TAIL GATE LOCK CATCH	Not Necessary	62.50 FL	*- FL
8	1		*REAR TAIL GATE INNER BOARD	Deformed / Torn	489.20 FL	*336.00 FL
9	2		*REAR TAIL GATE HINGE	Not Necessary	198.60 FL	*- FL
10	2		*REAR TAIL GATE ABSORBER	Not Necessary	739.00 FL	*- FL
11	2		*REAR TAIL GATE STOPPER	Not Necessary	59.00 FL	*- FL
12	2		*REAR NUMBER PLATE LAMP	Not Necessary	154.60 FL	*- FL
13	1		*REAR TAIL GATE WEATHERSTRIP	Not Necessary	341.70 FL	*- FL
14	1		*END PANEL	Badly Dented	925.00 FL	*345.00 FL
15	1		*END PANEL TOP GARNISH	Twisted	786.00 FL	*208.00 FL
16	2		*TAIL LAMP	Cracked	2,772.40 FL	*480.00 FL
17	2		*TAIL LAMP PANEL	Repair	654.00 FL	*- FL
18	2		*REAR FENDER	Repair	2,858.00 FL	*- FL
19	2		*REAR FENDER ARCH GARNISH	Not Necessary	390.40 FL	*- FL
20	2		*REAR FENDER INNER TRIM	Not Necessary	732.00 FL	*- FL
21	1		*REAR WINDSCREEN MOULDING	Necessary	210.30 FL	*110.00 FL
22	1		*REAR AIR VENT	Not Necessary	101.50 FL	*- FL
23	1		*REAR BUMPER	Distorted	1,486.00 FL	*741.00 FL
24	1		*REAR BUMPER SIDE BRACKET	Bent	85.70 FL	*85.70 FL
25	1		*REAR BUMPER DIFFUSER	Distorted	425.00 FL	*385.00 FL
26	1		*REAR BUMPER REINFORCEMENT	Cracked	782.30 FL	*415.00 FL
27	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	156.00 FL	*156.00 FL
28	1		*REAR BUMPER SPONGE	Not fitted	183.50 FL	*- FL
29	2		*REAR CORNER BUMPER	Deformed	370.00 FL	*304.00 FL
30	4		*REAR BUMPER PARKING SENSOR	Shorted (2 PCS ONLY)	788.00 FL	*378.00 FL
31	2		*REAR BUMPER REFLECTOR	Cracked	330.00 FL	*270.00 FL
32	1		*REAR BUMPER PARKING SENSOR HARDNESS WIRE	Not Necessary	189.00 FL	*- FL
33	1		*REAR BUMPER TOWING COVER	Deformed	78.80 FL	*30.00 FL
34	1		*REAR LUGGAGE PANEL	Crumpled / Buckled	686.00 FL	*555.00 FL
35	1		*REAR EXHAUST SILENCER	Not Necessary	896.00 FL	*- FL
36	2		*REAR EXHAUST CHROME PIPE	Not Necessary	370.60 FL	*- FL
37	2		*REAR EXHAUST RUBBER	Not Necessary	58.60 FL	*- FL
38	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	150.00 FS	*40.00 FS
39	1		*REAR NUMBER PLATE (RED PLATE) INCLUDE INSPECTION	Necessary	160.00 FS	*50.00 FS
40	1		*REAR END PANEL SEALANT	Necessary	350.00 FS	*50.00 FS
41	20		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
42	1		*SET REAR BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>22,001.50</b>	<b>6,605.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	2,119.15	643.57
<b>Total Parts (\$\$)</b>	<b>19,882.35</b>	<b>5,962.13</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	200.00	20.00
2	TUFF KOTE	New	200.00	90.00
3	REMOVE AND REFIX UPHOLSTERY	New	260.00	80.00
4	REMOVE AND REPLACE EXHAUST PIPE	New	160.00	0.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
6	REMOVE AND REFIX REVERSING SENSOR	New	150.00	50.00
7	TO REMOVE AND REPLACE SPARE PARTS AND PANEL BEATING	New	2,000.00	1,100.00
8	TO SPRAY PAINTING AND ETC	New	1,800.00	1,100.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,920.00</b>
				<b>2,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >