

ASS. REC. BY:

REF: LPC / 23000412/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

12/26

Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBA 3450KYr Regn: 05, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Toy Dynac.c. 2882Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 410700

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA7354803000763Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F. Hankook 195R 15x8Gravelander 155R 12x8 (H)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 4 4 mmL/Bal. 8 mmL/Bal. 4 4 mmD.O.A. 9/1/23D.O.I. 12/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA & EST not ready2/2 11/26 & 27/26 Car

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

: Fines

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Kp

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA DYNA

Engine/Chassis No.: JTFAT35Y803000765

Date of accident: 09.01.23

Damaged area: Rear

Date: 14.01.23

Claim Type: TP


VRN: GBA3450K

Not Withstand

11 Lm & 2700h

Resurvey After Paint

4 days



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tail gate 1582-60	1	\$ 1,997.00	\$ 1,997.00
2	Tail gate hinge	1	\$ 68.00	\$ 272.00
3	Tail gate stopper C 23	2	\$ 63.00	\$ 126.00
4	Tail gate stopper bracket	2	\$ 153.00	\$ 306.00
5	Tail gate lower panel 685-10	1	\$ 958.00	\$ 958.00
6	Tail lamp panel	2	\$ 383.00	\$ 766.00
7	Tail lamp C 225-60	2	\$ 373.00	\$ 746.00
8	Rear licence plate lamp	2	\$ 77.00	\$ 154.00
9	Rear floor panel	1	\$ 1,487.00	\$ 1,487.00
10	Rear licence plate base panel	1	\$ 150.00	\$ 150.00
11	Rear spare tyre carrier	1	\$ 486.00	\$ 486.00
12	Tail gate hinge pin	4	\$ 134.00	\$ 536.00
13	Tail gate lock	2	\$ 276.00	\$ 552.00
14	Tail gate lower member	1	\$ 1,714.00	\$ 1,714.00
15	Tail gate lower member hook	2	\$ 158.00	\$ 316.00
16	Exhaust silencer	1	\$ 782.00	\$ 782.00
17	Exhaust hanger	1	\$ 66.00	\$ 66.00
Subtotal				\$ 11,414.00
List discount				25.00%
Total				\$ 8,560.50

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear number plate	1	\$ 55.00	\$ 55.00
2	Tail gate "TOYOTA" sticker	1	\$ 180.00	\$ 180.00
3	Rear tailgate "70km/h" sticker	1	\$ 15.00	\$ 15.00
4	Rear tailgate "DYNA" sticker	1	\$ 15.00	\$ 15.00
5	Spare tyre	2	\$ 380.00	\$ 760.00
6	Reverse sensor	1	\$ 280.00	\$ 280.00
7	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,355.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove and replace, straighten and readjust exhaust pipe.	0.5	\$ <i>na</i> 100.00
4	To align rear cargo frame and to conduct chassis alignment on Car-O-Liner.	2	\$ <i>na</i> 400.00
5	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
6	To rust proof all affected portions after repair.	1	\$ 200.00
Total labour			\$ 2,750.00
Estimate Grand Total			\$ 12,665.50

6001

201

X

X

5501

601

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____