



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 4503R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	DAMAGED	131.00	131.00
2	FRONT FORKS	DISTORTED	854.00	854.00
1	FRONT FORK STEM	NOT NECESSARY	185.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	67.00	-
1	FRONT RIM BEARING	NOT NECESSARY	82.00	-
1	HEADLAMP	NOT NECESSARY	190.00	-
1	HEADLAMP BRACKET	NOT NECESSARY	82.00	-
1	HEADLAMP FAIRING	DAMAGED	138.00	138.00
1	FRONT SIGNAL LAMP	DAMAGED	39.20	39.20
1	ENGINE LOWER FAIRING	NOT NECESSARY	182.00	-
1	HANDLE BAR	DISTORTED	141.00	141.00
1	HANDLE BAR BRACKET	NOT NECESSARY	104.50	-
1	HAND BRAKE LEVER	DAMAGED	42.00	42.00
1	THROTTLE GRIP	NOT NECESSARY	32.00	-
1	SIDE MIRROR (SET)	DAMAGED	80.00	80.00
1	FUEL TANK UPPER GARNISH	DAMAGED	148.00	148.00
2	FUEL TANK SIDE COVER	DAMAGED	298.00	298.00
1	SIDE FAIRING	DAMAGED	162.30	162.30
1	FOOT BRAKE PEDAL	DAMAGED	72.00	72.00
1	FRONT FOOT REST	MISSING	89.60	89.60
1	MUFFLER PROTECTOR	DAMAGED	114.00	114.00
1	MUFFLER GARNISH	DAMAGED	89.00	89.00
	LESS 10% DISCOUNT		-	-239.81
			3,322.60	2,158.29
<u>SPECIAL NETT ITEMS</u>				
1	FRONT RIM (SN)	O/S TO REPAIR SEE LABOUR/ N/S DISTORTED	480.00	100.00
1	FRONT LICENCE PLATE (SN)	DAMAGED	15.00	10.00
1	FRONT TYRE (SN)	NOT NECESSARY	120.00	-
1	ERP UNIT (SN)	NOT NECESSARY	165.00	-

Report Ref No. CS3/ASM22006017/Rwp3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX (SN)	DAMAGED	300.00	150.00
1	STEERING CONE BEARING (SN)	NECESSARY	65.00	30.00
1	FRONT FORK OIL SEAL (SN)	NECESSARY	19.00	10.00
			1,164.00	300.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.	NOT NECESSARY	50.00	-
	TO REMOVE/REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT RIM (O/S).		450.00	300.00
	TO CARRY OUT BODY FRAME ALIGNMENT.		300.00	150.00
			800.00	450.00
GRAND TOTAL			5,286.60	2,908.29
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS3/ASM22006017/Rwp3m4-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.