

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI23000414/TNY3E2
Date: 14/03/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMM3952K	Insured Vehicle No :	SMG2290A
Date of Loss:	10/01/2023	Nature of Claim:	TP
		Claim No:	CDMPG23000068

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM3952K	Engine No:	G4FGKH737206
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF5416MK5044414
Reg. Date:	27/06/2019 (Man. Year: 2018)	Odometer:	98028 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	7,242.40	6,533.60	708.80	9.79	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,660.00	1,390.00	1,270.00	47.74	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	9,902.40	7,923.60	1,978.80	19.98	
Approved Total (Overridden) (S\$)		6,300.00			
	(S\$)	9,902.40	6,300.00	3,602.40	36.38
+ GST 8.00/8.00% (S\$)	792.19	504.00	288.19	36.38	
Nett Amount (S\$)	10,694.59	6,804.00	3,890.59	36.38	

INSPECTION

Date of Assignment:	12/01/2023	
Date Inspected:	12/01/2023	Inspected At: Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2023)
Parts: 143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMM3952K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP HID LH	Cracked	2,210.00 FL	*2,210.00 FL
2	1		*HEADLAMP BOTTOM RETAINER	N/S Necessary/O/SNot Necessary	106.00 FL	*53.00 FL
3	1		*SET HEADLAMP CLIP	Necessary	20.00 FL	*10.00 FL
4	1		*FRONT BUMPER	Deformed	872.00 FL	*872.00 FL
5	1		*FRONT BUMPER SIDE RETAINER	N/S Deformed/O/SNot Necessary	78.00 FL	*39.00 FL
6	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FL	*30.00 FL
7	1		*FRONT BUMPER BADGE	Necessary	58.00 FL	*58.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Dented	460.00 FL	*460.00 FL
9	1		*FRONT BUMPER SPONGE	Cracked	129.00 FL	*129.00 FL
10	1		*FRONT BUMPER LOWER GARNISH SKIRT	Cut	712.00 FL	*712.00 FL
11	1		*FRONT BUMPER SIGNAL LAMP LH	Cut	152.00 FL	*152.00 FL
12	1		*FRONT BUMPER SIDE GARNISH LH	Cut	139.00 FL	*139.00 FL
13	1		*FRONT BUMPER SENSOR (ORIGINAL) LH	Shorted	195.00 FL	*195.00 FL
14	1		*FRONT BUMPER SENSOR HOLDER LH	Necessary	46.00 FL	*46.00 FL
15	1		*FRONT FENDER LH	Bent	471.00 FL	*471.00 FL
16	1		*FRONT FENDER INNER SHIELD	Deformed	156.00 FL	*156.00 FL
17	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
18	1		*FRONT ABSORBER LH	Not Necessary	320.00 FL	*- FL
19	1		*FRONT LOWER ARM LH	Bent	385.00 FL	*385.00 FL
20	1		*FRONT KNUCKLE ARM LH	Distorted	392.00 FL	*392.00 FL
21	1		*FRONT WHEEL BEARING LH	Distorted	165.00 FL	*165.00 FL
22	1		*SPORT RIM	Cut	500.00 FS	*500.00 FS
23	1		*SPORT RIM TYRE	Not Necessary	320.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,956.00	7,204.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	713.60	670.40
Total Parts (\$\$)	7,242.40	6,533.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	500.00
2	SPRAY PAINTING	New	1,000.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	90.00	30.00
5	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	250.00	150.00
6	TO CHECK FOUR WHEEL ALIGNMENT	New	90.00	80.00
7	TO RESET AND ERASE FAULT CODE SYSTEM SENSOR	New	180.00	100.00
			Gross Labour Cost (\$)	1,390.00
				2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >