



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 2305D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	NOT NECESSARY	98.00	-
1	LEVER LH	NOT NECESSARY	28.00	-
1	LEVER RH	CUT	28.00	28.00
1	SET MIRROR	O/S GRAZED	110.00	110.00
1	FRONT COVER COMPLETE	CUT	112.00	112.00
1	FRONT STAY	NOT NECESSARY	65.00	-
1	FORK UNDER BRACKET	SERVICEABLE	194.00	-
1	FRONT FENDER COMPLETE	CUT	123.00	123.00
1	INNER SHIELD	DEFORMED	108.00	108.00
2	LEG SHIELD SIDE COVER ASSY @139.00	GRAZED/CRACKED	278.00	278.00
1	FRONT BOARD RH	CUT	83.00	83.00
1	SET FLOOR MAT RH	NECESSARY	32.00	32.00
1	FLOOR BOARD SIDE MOLE RH	CUT	68.00	68.00
1	PIILION FOOTREST RH	CUT	45.00	45.00
2	REAR SIDE COVER COMPLETE @82.00	CUT/ COME IN A SET	164.00	164.00
2	REAR SHOCK ABSORBER @211.00	NOT NECESSARY	422.00	-
1	EXHAUST MUFFLER ASSY	DENTED	485.00	485.00
1	EXHAUST MUFFLER GASKET	NECESSARY	14.00	14.00
1	MUFFLER PROTECTOR	CUT	86.00	86.00
	LESS 10% DISCOUNT		-254.30	-173.60
			2,288.70	1,562.40
2	FORK ASSY @377.00 (LOCAL REPAIR) (SN)	BENT	754.00	100.00
	LESS 10% DISCOUNT		-75.40	-
			678.60	100.00
<u>SPECIAL NETT ITEMS</u>				
1	SET STEERING CONE & BEARING (SN)	NECESSARY	100.00	80.00
1	BATTERY, YUASA YTZ6V (SN)	NOT NECESSARY	59.00	-
1	REAR TOP BOX (SN)	CUT	255.00	150.00

Report Ref No. CS3/ASM22005987/Rqp3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RACK (SN) <u>LABOUR</u> TOWING FEE. ALIGN STEERING COMPONENTS. RENEW DAMAGED PARTS & REPAIR AFFECTED AREAS.	NOT NECESSARY	150.00	-
			564.00	230.00
			80.00	40.00
			100.00	60.00
			450.00	300.00
		630.00	400.00	
GRAND TOTAL			4,161.30	2,292.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CS3/ASM22005987/Rqp3m4-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.