

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM23000429/Rwp3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	16/01/2023	
	ATTN: CHEN XINY	OU		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 3210R	Veh. Inspected	ı	AW 8484B
	Policy No.		Coverage (\$)		0.00
	Claim No.	S3M04HLA	Excess (\$)		0.00
	Assign From	CHEN XINYOU	Assign Date		12/01/2023
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA CZD300A / XMAX300	c.c		292
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	MH3SH0840LK012460	Colour		BLACK
	Odometer	28686 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	120/70-15	PIRELLI		4 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	140/70-14	PIRELLI		4 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
5.	. General Information				
	Accident Date	04/01/2023	Inspect Date /	Time	12/01/2023 ( 02:28 PM )
	Survey held at HUP HIN				
	BLK 1006 BUKIT MERAH LANE 2 #01-02 SINGAPORE 159762				
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM23000429/Rwp3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$ 

REGD Auto Consultant-SAE, Licensed Appraiser