

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23000430/AQY3Q2**Date:** 02/03/2023**REFERENCE**

Handling Insurer: ECICS Limited Policy No: MCV22A00018200
Claimant Vehicle No : SMM666G **Insured Vehicle No :** GBH9825L
 Date of Loss: 07/01/2023 Nature of Claim: TP Claim No: DMCV2300001H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM666G**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB6739848
 Reg. Date: 11/01/2019 (Man. Year: 2018) Chassis No: RU31319835
 Colour: White Odometer: 132956 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,247.36	8,204.00	15,043.36	64.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,350.00	3,050.00	3,300.00	51.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,597.36	11,254.00	18,343.36	61.98
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	29,597.36	9,000.00	20,597.36	69.59

INSPECTION

Date of Assignment: 19/01/2023
 Date Inspected: 09/01/2023 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM666G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,101.00 FL	*1,101.00 FL
2	1		*TAILGATE REVERSE CAMERA	Damaged	816.00 FS	*400.00 FS
3	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
4	1		*TAILGATE EMBLEM VEZEL	Necessary	69.00 FL	*69.00 FL
5	1		*TAILGATE EMBLEM HYBRID	Necessary	75.00 FL	*75.00 FL
6	1		*TAILGATE OUTER GARNISH	Cracked	396.00 FL	*396.00 FL
7	1		*TAILGATE OUTER MOULDING	Not Necessary	210.00 FL	*- FL
8	2		*TAILGATE SIDE LAMP	N/S Cracked / O/S Cut	728.00 FL	*728.00 FL
9	1		*TAILGATE DAMPER	Not Necessary	302.00 FL	*- FL
10	1		*TAILGATE INNER HOLDER	Not Necessary	52.00 FL	*- FL
11	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
12	1		*TAILGATE TOP LOCK	Damaged	145.00 FL	*145.00 FL
13	1		*TAILGATE LOWER LOCK	Not Necessary	24.70 FL	*- FL
14	1		*TAILGATE OUTER LOCK HANDLE	Not Necessary	103.70 FL	*- FL
15	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
16	1		*TAILGATE INNER TRIM	Cracked	398.60 FL	*398.60 FL
17	1		*TAILGATE INNER TRIM (SIDE)	N/S Deformed	242.00 FL	*121.00 FL
18	1		*TAILGATE INNER TOP TRIM	Not Necessary	185.20 FL	*- FL
19	1		*TAIL GATE WEATHER STRIP	Cut	168.40 FL	*168.40 FL
20	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	134.00 FL	*134.00 FL
21	1		*TAILGATE LOCK CONNECTOR	Cracked	217.00 FL	*135.00 FL
22	1		*BUZZER	Damaged	109.00 FL	*109.00 FL
23	1		*BUZZER WIRE HARNESS	Not Necessary	288.50 FL	*- FL
24	2		*TAIL LAMP	N/S Cracked / O/S Cut	950.00 FL	*950.00 FL
25	1		*REAR BUMPER	Distorted	777.00 FL	*777.00 FL
26	1		*REAR BUMPER REFLECTOR	N/S Cracked	302.20 FL	*151.10 FL
27	1		*REAR BUMPER SIDE	N/S Deformed	460.00 FL	*230.00 FL
28	2		*REAR BUMPER SIDE RETAINER	Necessary	114.00 FL	*114.00 FL
29	2		*REAR FENDER INNER TRIM	Cracked	640.00 FL	*640.00 FL
30	2		*REAR FENDER COWLING	Not Necessary	300.40 FL	*- FL
31	2		*REAR FENDER ARCED GARNISH	Not Necessary	369.40 FL	*- FL
32	1		*REAR END PANEL	Distorted	530.00 FL	*530.00 FL
33	1		*REAR END PANEL TOP GARNISH	Deformed	121.00 FL	*121.00 FL
34	1		*REAR FLOOR PANEL	Buckled	695.00 FL	*695.00 FL
35	1		*REAR FLOOR PANEL BOTTOM CROSSMEMBER	Repair	789.00 FL	*- FL
36	1		*REAR FLOOR TOWING PANEL	Repair	387.00 FL	*- FL
37	1		*REAR FLOOR SIDE PANEL LH	Repair	297.60 FL	*- FL
38	1		*REAR FLOOR PANEL BOTTOM GARNISH	Deformed	269.00 FL	*269.00 FL
39	1		*REAR FLOOR PANEL TOP BOARD	Deformed	300.40 FL	*300.40 FL
40	1		*REAR STORAGE BOX	Deformed	495.00 FL	*495.00 FL
41	1		*HYBRID CHARGER	Not Necessary	1,687.00 FL	*- FL
42	1		*HYBRID FAN ASSY COOLING	Not Necessary	416.00 FL	*- FL
43	1		*HYBRID DUCT ASSY AIR INTAKE	Not Necessary	100.80 FL	*- FL
44	1		*HYBRID DUCT ASSY IPU INTAKE	Not Necessary	187.20 FL	*- FL
45	1		*HYBRID CASE COMP IPU	Not Necessary	182.50 FL	*- FL
46	1		*HYBRID COVER COMP IPU	Not Necessary	228.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*HYBRID COVER COMP REAR	Not Necessary	170.30 FL	*- FL
48	1		*HYBRID BATTERY	Not Necessary	8,500.00 FL	*- FL
49	1		*REAR CHASSIS MEMBER LH	Repair	653.00 FL	*- FL
50	1		*REAR NUMBER PLATE	Bent	80.00 FS	*60.00 FS
51	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
52	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
53	1		*SETTAILGATE OUTER GARNISH CLIP	Necessary	80.00 FS	*20.00 FS
54	1		*SET TAILGATE OUTER MOULDING CLIP	Not Necessary	80.00 FS	*- FS
55	1		*SET TAILGATE INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
56	1		*SET TAILGATE INNER TRIM (SIDE) CLIP	Necessary	80.00 FS	*10.00 FS
57	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
58	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
59	1		*SET TAIL LAMP CLIP	Necessary	40.00 FS	*20.00 FS
60	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*60.00 FS
61	1		*SET REAR FENDER UPPER TRIM CLIP	Not Necessary	60.00 FS	*- FS
62	1		*SET REAR FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
63	1		*SET REAR FENDER ARCED GARNISH CLIP	Not Necessary	60.00 FS	*- FS
64	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
65	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
66	1		*REAR FLOOR PANEL SEALANT	Necessary	350.00 FS	*60.00 FS
67	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
68	1		*REAR FLOOR TOWING PANEL SEALANT	Not Necessary	80.00 FS	*- FS
69	1		*REAR FLOOR SIDE PANEL SEALANT LH	Not Necessary	80.00 FS	*- FS
70	1		*REAR EXHAUST CHROME PIPE (SPECIAL TYPE)	Not Necessary	350.00 FS	*- FS
71	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,257.70	9,987.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,010.34	1,783.50
Total Parts (\$\$)	23,247.36	8,204.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	900.00
3	TUFF COAT	New	250.00	80.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	120.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
10	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
12	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	80.00	0.00
13	TO REMOVE AND REFIX AND REPROGRAM HYBRIC SYSTEM	New	1,200.00	450.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			6,350.00	3,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >