

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG17004408/KPA3Q2-1  
**Date:** 06/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100449730
<b>Claimant Vehicle No :</b>	SHC5173R	<b>Insured Vehicle No :</b>	SJS9089S
Date of Loss:	01/03/2017	Nature of Claim:	TP
		Claim No:	6157676770SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC5173R</b>		
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Engine No:	M9R8839C001029
Reg. Date:	14/01/2014 (Man. Year: 2013)	Chassis No:	VF1ABL15AUC276640
Colour:	Metallic White/Red	Odometer:	156742 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,865.89	866.39	11,999.50	93.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,870.00	480.00	6,390.00	93.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,735.89</b>	<b>1,346.39</b>	<b>18,389.50</b>	<b>93.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		
<b>(S\$)</b>	19,735.89	1,100.00	18,635.89	94.43
<b>+ GST 7.00/7.00% (S\$)</b>	1,381.51	77.00	1,304.51	94.43
<b>Nett Amount (S\$)</b>	<b>21,117.40</b>	<b>1,177.00</b>	<b>19,940.40</b>	<b>94.43</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$101.46/day) (S\$)</b>		304.38		
<b>(S\$)</b>		1,631.38		
<b>Liable Amount (50.00%) (S\$)</b>		<b>815.69</b>		
<b>Global Sum Settlement (S\$)</b>		<b>820.00</b>		

**INSPECTION**

Date of Assignment:	02/03/2017		
Date Inspected:	02/03/2017	Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled / Dented	852.66 FL	*852.66 FL
2	1		*BUMPER LOWER REAR	Serviceable	591.41 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	87.29 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER)	Serviceable	104.59 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	34.61 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	33.55 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)	Serviceable	104.59 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	34.61 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	33.55 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	598.09 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	173.81 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	173.81 FL	*- FL
13	1		*BOOT REAR	Repair	2,209.75 FL	*- FL
14	1		*BOOT FINISHER (MOULDING)	Serviceable	429.90 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	248.50 FL	*- FL
16	1		*BOOT REFLECTOR LAMP RH	Serviceable	379.50 FL	*- FL
17	1		*BOOT BADGE RENAULT	Not Necessary	173.35 FL	*- FL
18	1		*BOOT BADGE	Not Necessary	173.35 FL	*- FL
19	1		*TAILLAMP RH	Serviceable	425.04 FL	*- FL
20	1		*TAILLAMP LH	Serviceable	425.04 FL	*- FL
21	1		*EXHAUST REAR	Repair	5,760.00 FL	*- FL
22	1		*EXHAUST CAP REAR	Repair	177.30 FL	*- FL
23	1		*SET PARKING AID	Serviceable	600.00 FS	*- FS
24	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
25	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
26	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
27	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
28	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
29	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
30	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
31	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
32	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
33	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
34	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,188.32</b>	<b>951.66</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,322.43	85.27
<b>Total Parts (\$)</b>	<b>12,865.89</b>	<b>866.39</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	220.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,800.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTER EXHAUST PIPE.	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >