

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000440/KPA3Q2**Date:** 24/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900095210		
Claimant Vehicle No :	GBH8632H	Insured Vehicle No :	SJT5801Z		
Date of Loss:	05/01/2023	Nature of Claim:	TP	Claim No:	4284775457SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH8632H	Engine No:	1KD2825585
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y50K211606
Reg. Date:	18/10/2018 (Man. Year: 2018)	Odometer:	84174 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Michelin 9 mm	Rear Left Side:	Falken 7/7 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Falken 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,444.66	1,407.40	2,037.26	59.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	770.00	930.00	54.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,144.66	2,177.40	2,967.26	57.68
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
Nett Liability (S\$)		2,497.40		

INSPECTION

Date of Assignment:	10/01/2023		
Date Inspected:	10/01/2023	Inspected At:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	727.10 FL	*698.10 FL
2	1		*FRONT BUMPER RH INNER BRACKET	Repair	292.10 FL	*- FL
3	1		*RH HEADLAMP	Cut	1,145.10 FL	*1,145.10 FL
4	1		*FRONT RH CORNER PANEL	Repair	258.20 FL	*- FL
5	1		*FRONT RH DOOR	Repair	1,450.45 FL	*- FL
6	1		*FRONT RH DOOR HINGE BOTTOM	Repair	74.10 FL	*- FL
7	1		*FRONT RH DOOR CHECKER	Serviceable	145.00 FL	*- FL
8	1		*FRONT RH DOOR WEATHERSTRIP	Serviceable	169.40 FL	*- FL
9	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
10	1		*FRONT RH STEP GARNISH	Serviceable	218.10 FL	*- FL
11	1		*FRONT RH DOOR LOWER COMPANY BLACK STICKER	Necessary	40.00 FS	*25.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	4,579.551,868.20
					- List Item Discount on L Items 25.00/25.00% (\$)	1,134.89460.80
					Total Parts (\$)	3,444.661,407.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE /REFIT ,PANEL BEATING ,KNOCKING AND REPLACEMENT OF DAMAGES	New	700.00	350.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	800.00	400.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE ,REFIT FRONT RH DOOR FITTINGS	New	80.00	0.00
5	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			1,700.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >