

ASS. REC. BY:

REF:

A/G / 23000440/KP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1.1% % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 863214Yr Regn: 10.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Dyna

c.c

2982Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 84174

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT 35450K 211606Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: MIC 195R15X8R: Falken 155R12X 80D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 7 7 mmL/Bal. 9 mmL/Bal. 7 7 mmD.O.A. 3/1/23D.O.I. 10/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 PM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/11 @ 2177.40 Cash

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Business Regn. No: 081026001

REPAIR ESTIMATE GBH8632H

No.	Qty	List Items	Unit Price	Amount	Remarks
1	1	Front bumper	\$ Bu	727.10	✓
2	1	Front bumper RH inner bracket	\$ n	292.10	X
3	1	RH headlamp	\$ n	1,145.10	✓
4	1	Front RH corner panel	\$ n	258.20	X
5	1	Front RH door	\$ n	1,450.45	X
6	1	Front RH door hinge bottom	\$ n	74.10	X
7	1	Front RH door checker	\$ n	145.00	X
8	1	Front RH door weatherstrip	\$ n	169.40	X
9	1 set	Front RH door inner trim board clips	\$ n	60.00	X
10	1	Front RH step garnish	\$ n	218.10	X
			\$	4,539.55	
Less 25%			\$	1,134.89	
Total :			\$	3,404.66	

11	1	Front RH door lower company black sticker	\$	<i>112</i>	40.00	<i>2552</i>
----	---	---	----	------------	-------	-------------

1	Labour Charges for remove/refit, panel beating, knocking and replacement of damages.	\$	700.00	350
2	To putty and spray Spray Paintings charges.	\$	800.00	400
3	To check wirings and lightings.	\$	40.00	20
4	To remove, refit front RH door fittings.	\$	na 80.00	X
5	To supply and apply anti rust treatment	\$	na 80.00	X
	Total :	\$	1,700.00	

Total Parts and Labour : \$ 5,144.66

Not Ashamed
Purvey B & pains
3 day

2177.40

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: