

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG23000441/AQP3M4**Date:** 03/08/2023**REFERENCE**

Insured/Claimant:	LEE ZHOU RUI AARON	Policy No:	
Date of Loss:	06/01/2023	Nature of Claim:	OD Claim No: 9380885179SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMS7605E</b>	Engine No:	DEM033860
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF45MA080873
Reg. Date:	21/07/2022 (Man. Year: 2021)	Odometer:	8064 km
Colour:	Bronze		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$230,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,936.00	15,153.60	13,782.40	47.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,612.00	4,262.00	8,350.00	66.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>41,548.00</b>	<b>19,415.60</b>	<b>22,132.40</b>	<b>53.27</b>
<b>- Excess (\$\$)</b>	550.00	550.00	0.00	0.00
<b>(\$\$)</b>	40,998.00	18,865.60	22,132.40	53.98
<b>+ GST 8.00/8.00% (\$\$)</b>	3,279.84	1,509.25	1,770.59	53.98
<b>Nett Amount (\$\$)</b>	<b>44,277.84</b>	<b>20,374.85</b>	<b>23,902.99</b>	<b>53.98</b>

**INSPECTION**

Date of Assignment:	13/01/2023	
Date Inspected:	12/01/2023	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,515.00 FS	*2,012.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	416.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	84.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE	Not Necessary	231.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	310.00 FS	*247.60 FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	166.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	310.00 FS	*- FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	318.00 FS	*- FS
9	2		*FRONT BUMPER TRIM - LH / RH	Not Necessary	114.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,861.00 FS	*1,488.80 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	224.00 FS	*178.80 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	953.00 FS	*762.00 FS
13	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Cracked	151.00 FS	*120.40 FS
15	1		*CAUTION SIGN STICKER	Necessary	17.00 FS	*13.28 FS
16	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*7.12 FS
17	1		*FRONT BUMPER BRACKET	Cracked	163.00 FS	*130.00 FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	68.00 FS	*54.00 FS
19	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	543.00 FS	*- FS
20	2		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	543.00 FS	*- FS
21	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
22	1		*SET FRONT BUMPER WIRING	Not Necessary	648.00 FS	*- FS
23	1		*HORN HIGH TONE - LH	Not Necessary	142.00 FS	*- FS
24	1		*HORN BRACKET - LH	Not Necessary	35.00 FS	*- FS
25	1		*BONNET	Dented	3,489.00 FS	*2,791.20 FS
26	1		*BONNET IMPACT PROTECTION - CENTER / LH / RH 3PIECES	Necessary	101.00 FS	*80.00 FS
27	1		*BONNET STRIKER - LH	Not Necessary	60.00 FS	*- FS
28	1		*BONNET LOCK	Not Necessary	241.00 FS	*- FS
29	1		*BONNET BOWDEN CABLE	Not Necessary	67.00 FS	*- FS
30	1		*BONNET RELEASE LEVER	Not Necessary	16.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	67.00 FS	*- FS
32	1		*BONNET RELEASE CABLE COVER	Not Necessary	12.00 FS	*- FS
33	1		*HEADLIGHT COVER - LH	Not Necessary	52.00 FS	*- FS
34	1		*HEADLIGHT - LH	Cracked	8,666.00 FS	*6,932.80 FS
35	2		*LIFT CYLINDER - LH / RH	Not Necessary	488.00 FS	*- FS
36	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	111.00 FS	*- FS
37	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Damaged	22.00 FS	*17.36 FS
38	1		*LOCK CARRIER	Not Necessary	1,569.00 FS	*- FS
39	1		*LOCK CARRIER SUPPORT	Not Necessary	45.00 FS	*- FS
40	1		*A/C CONDENSER	Not Necessary	724.00 FS	*- FS
41	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	197.00 FS	*- FS
42	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	405.00 FS	*- FS
43	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	293.00 FS	*- FS
44	1		*CHARGE AIR COOLER	Not Necessary	692.00 FS	*- FS
45	1		*CHARGE AIR COOLER PRESSURE PIPE - LH	Not Necessary	495.00 FS	*- FS
46	6		*READY-MIX COOLANT	Not Necessary	326.00 FS	*- FS
47	1		*RADIATOR AIR GUIDE - LH INNER	Not Necessary	38.00 FS	*- FS
48	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Deformed	50.00 FS	*39.84 FS
49	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	25.00 FS	*- FS
50	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	38.00 FS	*- FS
51	1		*FRONT BUMPER BRACKET - LH	Bent	269.00 FS	*215.20 FS
52	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
53	1		*SUNDRIES	Necessary	400.00 FS	*3.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 28,936.00 15,153.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SNESOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM	New	1,400.00	0.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
6	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REPAIR LHS FRONT FENDER (Supplementary)	New	700.00	0.00
9	TO RESPRAY LHS FRONT FENDER (Supplementary)	New	1,400.00	550.00
10	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT BUMPER REINFORCEMENT BEAM BRACKET (Supplementary)	New	480.00	480.00
11	TO RE-COAT FOR AFFECTED AREA (SUPPLY BY OWNER) (Supplementary)	New	210.00	210.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,612.00</b>	<b>4,262.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >