



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7449T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CUT / DENTED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER UNDER MOULDING	NOT NECESSARY	155.00	-
2	REAR BUMPER BRACKET LH / RH @\$55.80	NOT NECESSARY	111.60	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR FOG LAMP	NOT NECESSARY	201.50	-
1	BOOTLID	TO REPAIR SEE LABOUR	2,549.70	-
1	BOOTLID EMBLEM HYBRID	NOT NECESSARY	24.30	-
1	BOOTLID EMBLEM IONIQ	NOT NECESSARY	31.30	-
2	REAR NUMBER PLATE LAMP @\$85.30	NOT NECESSARY	170.60	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	41.45	-
1	REAR BLIND SPOT RADAR RH	NOT NECESSARY	1,784.40	-
	LESS 20% DISCOUNT		-1,279.46	-186.53
			5,117.84	746.12
<u>SPECIAL NETT ITEMS</u>				
1	BOOTLD COMFORT / TEL NUMBER STICKER (SN)	NOT NECESSARY	60.00	-
1	BOOTLID LID COMFORT APP STICKER (SN)	NOT NECESSARY	40.00	-
1	BOOTLID ADVERTISEMENT LOGO (SN)	NECESSARY	80.00	80.00
2	REAR FENDER ADVERTISEMENT LH / RH @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE W/HOLDER (SN)	CRACKED	55.00	55.00
1	REAR REVERSE SENSOR (SN)	SCRATCHED	180.00	180.00
			665.00	565.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID.		900.00	700.00
	SPRAY PAINTING CHARGE.		800.00	500.00
	REMOVE / REFIX REAR WINDSCREEN UPPER / LOWER.	NOT NECESSARY	190.00	-
	RESET / DIAGNOSE.	NOT NECESSARY	240.00	-

Report Ref No. CS/SMR23000442/Svy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.	NOT NECESSARY	90.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			2,280.00	1,230.00
GRAND TOTAL			8,062.84	2,541.12
RECOMMENDED COST OF REPAIRS				2,541.12

Report Ref No. CS/SMR23000442/Svy3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.