

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 6424Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	R/H REAR DOOR	DENTED	976.00	976.00
1	R/H REAR DOOR INNER LOCK	JAMMED	312.00	312.00
1	R/H REAR DOOR CHECKER	BENT	97.00	97.00
1	R/H REAR DOOR WEATHERSTRIP	DEFORMED	188.00	188.00
1	R/H REAR DOOR WINDOW REGULATOR W/ MOTOR	BENT	562.00	562.00
1	R/H REAR DOOR WINDOW OUTER SEAL	BENT	110.00	110.00
1	R/H REAR DOOR INNER TRIM BOARD	TORN	552.00	552.00
1	R/H REAR DOOR INNER TRIM CONTROL PANEL	SERVICEABLE	124.00	-
1	SET R/H REAR DOOR INNER TRIM BOARD CLIPS	NOT NECESSARY	32.00	-
2	R/H REAR DOOR HINGES @S\$55.00	BENT	110.00	110.00
1	R/H REAR DOOR QTR GLASS W/ MOULDING (CAN'T SEE DAMAGE)	SERVICEABLE	565.00	-
1	R/H REAR DOOR SPEAKER	SERVICEABLE	243.00	-
1	R/H FRONT DOOR	TO REPAIR SEE LABOUR	992.00	-
1	R/H SIDE SKIRT	DEFORMED	627.00	627.00
1	R/H ROCKER PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-	-353.40
			5,490.00	3,180.60
	<u>LABOUR</u>			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF R/H FRONT DOOR AND R/H ROCKER PANEL.		1,400.00	400.00
	TO CHECK WIRING AND REWIRE.		60.00	20.00
	TO REMOVE AND REINSTALL FRONT DOOR COMPONENTS.	NOT NECESSARY	80.00	-
	TO REMOVE AND REINSTALL REAR DOOR COMPONENTS.		80.00	60.00
	TO APPLY ANTI-RUST.		80.00	40.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		1,200.00	800.00
			2,900.00	1,320.00
	GRAND TOTAL		8,390.00	4,500.60

Report Ref No. CS3/SMO22007586/Uwy3m4-1





RECOMMENDED COST OF LUMP SUM REPAIRS		3,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/SMO22007586/Uwy3m4-1

CHUA KANG SENG

Licensed Appraiser