

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	R	Ref:	CS3/LPC23000444/Tny3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	D	Date:	19/01/2023	
			C	Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 6675H	Veh. Inspected		SGU 291H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/026831	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		13/01/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MR053REH604599065	Colour		BROWN	
	Odometer	25303 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S REAR PORTION.				
5.	General Information					
	Accident Date	10/01/2023	Inspect Date / Ti	me	17/01/2023 (03:30 PM)	
	Survey held at	SIN HENG LONG MOTOR WORK				
		BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-287/305 SINGAPORE 569535				
5a.	•	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23000444/Tny3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor