

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI23000449/UVP3Q2**Date:** 20/02/2023**REFERENCE**

Insured/Claimant:	ALI AMRAN BIN MOHAMED SHARIF	Policy No:	DMPCSNW00074482200		
Date of Loss:	06/01/2023	Nature of Claim:	OD	Claim No:	SNM23D200187/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN8309R	Engine No:	R18A1796733
Make & Model:	HONDA STREAM, 1.8 RSZ (A)	Chassis No:	RN61087284
Reg. Date:	27/02/2009 (Man. Year: 2008)	Odometer:	204426 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	S\$10,800.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50Z R17	Rear Tyre Size:	205/50Z R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,941.00	14,621.00	320.00	2.14
Miscellaneous Items	12.60	12.60	0.00	0.00
Labour	886.20	852.60	33.60	3.79
Paintwork Labour	723.76	723.76	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,563.56	16,209.96	353.60	2.13
Approved Total (Overridden) (S\$)		7,000.00		
- Excess (S\$)	0.00	3,750.00	-3,750.00	
(S\$)	16,563.56	3,250.00	13,313.56	80.38
+ GST 8.00/8.00% (S\$)	1,325.08	260.00	1,065.08	80.38
Nett Amount (S\$)	17,888.64	3,510.00	14,378.64	80.38

INSPECTION

Date of Assignment:	13/01/2023	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	13/01/2023	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	10.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2023)
Parts:	M1-MPV	HONDA STREAM 1.8 RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN8309R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		14,841.00 F	*14,521.00 F
2	1		*SUNDRY		100.00 F	*100.00 F
F=Franchise part.						
Total Parts (S\$)					14,941.00	14,621.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	RUSTPROOFING	12.60	12.60
Sub Total (\$\$)			12.60	12.60

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT LABOUR CHARGE	New	723.76	723.76
<u>Labour Items</u>				
2	TOTAL LABOUR CHARGE	New	886.20	852.60
Gross Labour Cost (\$\$)			1,609.96	1,576.36

Report was unsubmitted during this print-out.

< END OF ESTIMATES >