



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 869G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EXHAUST MUFFLER	REPAIRED SEE LABOUR	554.00	-
1	EXHAUST MUFFLER COVER	REPAIRED SEE LABOUR	95.00	-
1	REAR MUDGUARD	REPLACED	198.00	198.00
1	REAR MUDGUARD REFLECTOR	REPLACED	32.00	32.00
1	TAILLAMP ASSY	REPLACED	596.00	385.00
	LESS 10% DISCOUNT		-147.50	-61.50
			1,327.50	553.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NO PLATE (SN)	REPLACED	20.00	20.00
			20.00	20.00
	<u>LABOUR</u>			
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF EXHAUST MUFFLER AND EXHAUST MUFFLER COVER.		300.00	200.00
	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.	NOT NECESSARY	200.00	-
			500.00	200.00
	GRAND TOTAL		1,847.50	773.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			620.00

Report Ref No. CS/ASM23000454/Avp3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.