



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (S) PTE LTD 10 MARINA BOULEVARD, #48-01, MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: CHONG ARNOLD			Ref: CS/ASM23000454/Avp3e2 Date: 01/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SHD 3362U	Veh. Inspected	FBT 869G	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03NQP	Excess (\$)	0.00	
Assign From	CHONG ARNOLD	Assign Date	13/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA NMAX	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MH3SG5680MK096198	Colour	BLACK	
Odometer	31257 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R13	IRC	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70 R13	IRC	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	03/12/2021	Inspection Date	30/01/2023	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		