



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23000457/Tvy3e2 Date: 26/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBK 9307A	Veh. Inspected	SBD 4488E
Policy No.		Coverage (\$)	0.00
Claim No.	D23000208MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	13/01/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GK81005073	Colour	BLUE
Odometer	83971 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/50 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/50 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/50 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/50 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/01/2023	Inspection Date	08/02/2023
Survey held at	160 Sin Ming Drive #06-02 Sin Ming Autocity		
Repairer	MBM WHEELPOWER PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	