

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S2M040QZ Date: 23rd February 2023

Our Ref: CS3/ASM22004465/Twp3m4-1

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard #48-01 Marina Bay Financial Centre Tower 2 Singapore 018983 (The Motor Claims Department)

Attn: Ang Yvonne

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBH 34L INSURED VEHICLE: SHA 980X

ACCIDENT DATE: 10/05/2022

We thank you for your instruction on 12/01/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBH 34L from Impact Analysis Consulting Pte Ltd.
- b) Singapore Accident Statement of Vehicles GBH 34L, SHA 980X, SMF 5394U and XE 5254R.
- c) Police Report of Vehicles GBH 34L and XE 5254R.
- d) Final Repair Bill of GBH 34L from M/s Garage 13 Pte Ltd.
- e) Colour damaged vehicle photographs of GBH 34L.

Pre-Repair Inspection Date: 12/05/2022 at M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier Singapore, 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBH 34L

Make & Model : Toyota Dyna 150 5MT

Year of Registration : 2017

Chassis Number : JTFAT35Y10K209612

Engine Capacity : 2982 cc

- 2. We recommend that the repairs of the entire damage require about <u>10 (Ten)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.