

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000463/KVP3Q2
Date: 20/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00001732200
Claimant Vehicle No :	PC7518Y	Insured Vehicle No :	SMS2760Y
Date of Loss:	11/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200338/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7518Y	Engine No:	4P10D49717
Make & Model:	MITSUBISHI ROSA, 3.0 D BE641JRMDEE (A)	Chassis No:	BE641JK30503
Reg. Date:	03/12/2018 (Man. Year: 2018)	Odometer:	152062 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/85 R16	Rear Tyre Size:	205/85 R16 (D)
Front Left Side:	Michelin 9 mm	Rear Left Side:	Yokohama 9/9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Yokohama 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,112.90	4,872.62	6,240.28	56.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,100.00	1,400.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,612.90	5,972.62	7,640.28	56.13
Approved Total (Overridden) (S\$)		4,750.00		
Nett Amount (S\$)	13,612.90	4,750.00	8,862.90	65.11

INSPECTION

Date of Assignment:	13/01/2023	
Date Inspected:	18/01/2023 Inspected At:	SERVE YOU MOTOR PTE LTD (HQ) BLK 5033 ANG MO KIO INDUSTRIAL PARK 2, #01-265 Singapore 569536
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Feb 2023)	
Parts:	N/A	MITSUBISHI ROSA 3.0 D BE641JRMDEE (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7518Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Bent	3,800.00 FL	*2,533.80 FL	
2	1		*REAR BUMPER REINFORCEMENT	Repair	880.00 FL	*- FL	
3	1		*REAR BUMPER BRACKET	Repair	440.00 FL	*- FL	
4	1		*REAR EMERGENCY DOOR	Bent	4,500.00 FL	*2,858.00 FL	
5	1		*REAR END PANEL	Repair	1,680.00 FL	*- FL	
6	1		*END PANEL TOP PLATE	Serviceable	280.00 FL	*- FL	
7	1		*DOOR LOCK	Repair	318.00 FL	*- FL	
8	1		*REAR DOOR LOWER GARNISH	Serviceable	283.00 FL	*- FL	
9	1		*REAR EMERGENCY DOOR STICKER	Necessary	150.00 FS	*20.00 FS	
					Sub Total (\$\$)	12,331.00	5,411.80
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,218.10	539.18
					Total Parts (\$\$)	11,112.90	4,872.62

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION .TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,000.00	500.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON REAR DAMAGED PORTION	New	1,500.00	600.00
			Gross Labour Cost (S\$)	2,500.00
				1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >