

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000465/RVP3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00040022203

Claimant Vehicle No : SNF5329Y **Insured Vehicle No :** GBJ4308K

Date of Loss: 12/01/2023 Nature of Claim: TP Claim No: SNM23D200336/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF5329Y**

Make & Model: JAGUAR E-PACE, 2.0 S (A) Engine No: 210129C0241PT153

Reg. Date: 01/06/2022 (Man. Year: 2022) Chassis No: SADFB2AS6N1031436

Colour: Blue Odometer: 5849 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,791.78	11,350.71	14,441.07	55.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,901.00	7,301.00	6,600.00	47.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	39,692.78	18,651.71	21,041.07	53.01
+ GST 8.00/8.00% (S\$)	3,175.42	1,492.14	1,683.28	53.01
Nett Amount (S\$)	42,868.20	20,143.85	22,724.35	53.01

INSPECTION

Date of Assignment: 13/01/2023

Date Inspected: 18/01/2023 Inspected At: 45 LENG KEE ROAD
SINGAPORE 159103
Repairer:Wearnes Automotive Pte Ltd (Leng Kee)

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2023)
Parts:	M1-SUV	JAGUAR E-PACE 2.0 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF5329Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE & HOLDER	Not Necessary	60.00 FS	*- FS
2	1		**D* PRIMER GLASS & P	Necessary	46.90 FS	*42.21 FS
3	2		*ADHESIVE AND SEALER	Necessary	385.80 FS	*347.22 FS
4	1		*GLASS -BACKLIGHT E-PA	Necessary	1,128.10 FS	*1,015.29 FS
5	1		*PANEL -TAILGATE E-PAC	Bent	3,994.70 FS	*3,595.23 FS
6	1		*BADGE -E-PACE	Necessary	216.90 FS	*195.21 FS
7	1		*BADGE -HALF LEAPER	Necessary	203.60 FS	*183.24 FS
8	1		*BADGE	Necessary	182.90 FS	*164.61 FS
9	1		*HARNESS REAR BUMPER	Not Necessary	599.30 FS	*- FS
10	1		*MICROSWITCH	Not Necessary	325.30 FS	*- FS
11	1		*COVER	Not Necessary	162.80 FS	*- FS
12	1		*LATCH	Cut	334.50 FS	*301.05 FS
13	1		*ACTUATOR	Not Necessary	208.90 FS	*- FS
14	1		*CLAMP	Not Necessary	29.50 FS	*- FS
15	1		*CAMERA	Not Necessary	1,442.10 FS	*- FS
16	1		*GASKET	Not Necessary	20.70 FS	*- FS
17	1		*BEZEL	Not Necessary	202.50 FS	*- FS
18	1		*BEAM -BUMPER REAR	Bent	785.40 FS	*706.86 FS
19	1		*SEAL -TAILGATE	Not Necessary	249.90 FS	*- FS
20	1		*LAMP -TAIL LH	Not Necessary	864.70 FS	*- FS
21	1		*LAMP -TAIL RH	Not Necessary	864.70 FS	*- FS
22	1		*LAMP -TAIL LH	Scratched	775.80 FS	*698.22 FS
23	1		*LAMP -TAIL RH	Cracked	775.80 FS	*698.22 FS
24	2		*LAMP-TRUNK NUMBER PL	Cracked	93.40 FS	*84.06 FS
25	2		*STUD-SPECIAL	Necessary	106.40 FS	*95.76 FS
26	1		*BUMPER -REAR	Deformed	2,666.70 FS	*2,400.03 FS
27	1		*PANEL -VALANCE	Cut	199.10 FS	*179.19 FS
28	1		*BLADE -BUMPER	Not Necessary	396.70 FS	*- FS
29	1		*COVER -TOWING EYE	Not Necessary	42.30 FS	*- FS
30	1		*FINISHER LH (SILVER)	Not Necessary	221.50 FS	*- FS
31	1		*FINISHER RH (SILVER)	Not Necessary	221.20 FS	*- FS
32	1		*MOULDING LH SIDE INS	Not Necessary	98.30 FS	*- FS
33	1		*MOULDING RH SIDE INS	Not Necessary	97.90 FS	*- FS
34	1		*MOUNTING CTR BRACKET	Cracked	191.10 FS	*171.99 FS
35	1		*INSERT -PLASTIC BRACK	Cracked	245.50 FS	*220.95 FS
36	1		*BRACKET -BMPR MNTING	Not Necessary	132.10 FS	*- FS
37	1		*BRACKET -BMPR MNTING	Not Necessary	132.10 FS	*- FS
38	1		*BRACKET -BUMPER LH	Cracked	156.60 FS	*140.94 FS
39	1		*BRACKET -BUMPER RH	Not Necessary	156.60 FS	*- FS
40	15		*BUMPER NUT XF	Necessary	91.50 FS	*82.35 FS
41	1		*SILENCER -EXHAUST	Not Necessary	3,646.50 FS	*- FS
42	1		*CLAMP -EXHAUST	Not Necessary	237.40 FS	*- FS
43	1		*HEATSHIELD	Not Necessary	479.30 FS	*- FS
44	1		*FINISHER -TRUNK	Not Necessary	656.50 FS	*- FS
45	4		*SENSOR	Not Necessary	1,440.40 FS	*- FS
46	1		*ANTENNA	Not Necessary	193.80 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BEZEL LATCH	Cut	28.08 FS	*28.08 FS
					F=Franchise part. S=SpcNett.	
Total Parts (S\$)					25,791.78	11,350.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACED TAILGATE ,RR BUMPER RR AEROBLADE ,RR LOWER COVER ,EMBLEM ,TAILGATE LAMP LH /RH,TAIL LAMP LH/RH ,ETC	New	4,200.00	2,600.00
2	TO REPLACE TAILGATE ,RR BUMPER RR FENDER LH/RH	New	4,500.00	2,000.00
3	TO REMOVE & TRANSFER TAILGATE INTERIOR COMPONENTS	New	500.00	500.00
4	TO REPLACE RR WINDSCREEN ,ETC	New	1,300.00	1,300.00
5	TO INSTALL RR WINDSCREEN FILM	New	280.00	280.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
7	TO REMOVE & REPLACE EXHAUST PIPE ,ETC	New	2,500.00	0.00
Gross Labour Cost (\$\$)			13,901.00	7,301.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >