

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23000474/NVY3Q2**Date:** 24/02/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000208
Claimant Vehicle No :	SHC7980P	Insured Vehicle No :	SLQ3318H
Date of Loss:	03/01/2023	Nature of Claim:	TP
		Claim No:	M2300089

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7980P	Engine No:	G4LEKU391111
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU184560
Reg. Date:	30/09/2020 (Man. Year: 2019)	Odometer:	256051 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,565.76	1,545.92	5,019.84	76.45
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,490.00	1,680.00	810.00	32.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,066.76	3,236.92	5,829.84	64.30
+ GST 8.00/8.00% (S\$)	725.34	258.95	466.39	64.30
Nett Amount (S\$)	9,792.10	3,495.87	6,296.23	64.30

INSPECTION

Date of Assignment:	14/01/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	05/01/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2023)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7980P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
2	2		*REAR BUMPER BRACKET LH/RH	Serviceable	111.60 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Deformed	394.80 FL	*394.80 FL
5	1		*REAR BUMPER REINFORCEMENT STAYLH/RH	N/S Bent / O/S Serviceable	276.20 FL	*138.10 FL
6	1		*BOOTLID COVER	Repair	2,549.70 FL	*- FL
7	1		*BOOTLID LOCK UPPER	Serviceable	224.00 FL	*- FL
8	1		*BOOT LID H EMBLEM	Not Necessary	28.00 FL	*- FL
9	1		*BOOT LID HYBIRD EMBLEM	Necessary	24.30 FL	*24.30 FL
10	1		*BOOT LID IONIQ EMBLEM	Necessary	31.30 FL	*31.30 FL
11	1		*REAR BUMPER CENTRE MOULDING	Cracked	451.25 FL	*451.25 FL
12	1		*REAR BUMPER LOWER MOULDING	Cracked	155.00 FL	*155.00 FL
13	1		*REAR TOW HOOK COVER	Serviceable	98.80 FL	*- FL
14	1		*REAR BUMPER FOG LAMP	Serviceable	201.50 FL	*- FL
15	2		*REAR NUMBER PLATE LAMP LH/RH	Serviceable	171.00 FL	*- FL
16	1		*REAR FENDER AIR DUCT LH	Serviceable	87.30 FL	*- FL
17	1		*REAR BLIND SPOT RADAR LH	Serviceable	1,784.40 FL	*- FL
18	1		*REAR END PANEL	Serviceable	532.00 FL	*- FL
19	2		*REAR BUMPER REFLECTOR LH/RH	Serviceable	82.90 FL	*- FL
20	1		*REAR SMART KEY ANTENNA	Serviceable	40.50 FL	*- FL
21	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
22	1		*REAR NUMBER PLATE W/HOLDER	Cracked	55.00 FS	*55.00 FS
23	1		*REAR REVERSE SENSOR	Serviceable	180.00 FS	*- FS
24	1		*BOOTLID BOOKING APP STICKER	Necessary	40.00 FS	*40.00 FS
25	1		*BOOTLID COMFORT/TEL NO STICKER	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,110.95	1,881.15
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,545.19	335.23
Total Parts (\$\$)	6,565.76	1,545.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	1,050.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK WIRING AND LIGHTING	New	60.00	0.00
4	REMOVE/REFIC REAR WINDSCREEN GLASS BIG/ SMALL	New	180.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
6	TUFF COATING	New	90.00	40.00
7	TOWING FEES	New	60.00	60.00
8	DIAGNOSE/RESET BLIND SPOT RADAR	New	240.00	0.00
Gross Labour Cost (\$\$)			2,490.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >