

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23000478/RVY3E2**Date:** 31/05/2023**REFERENCE**

Insured/Claimant: MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No: SP2003907937

Date of Loss: 13/01/2023

Nature of Claim: OD Claim No: 202332004529

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGA3030E**

Make & Model: MERCEDES-BENZ E300, 2.0 (A)

Engine No: 27492032014190

Reg. Date: 29/11/2022 (Man. Year: 2022)

Chassis No: W1K2130532B048273

Colour: Blue

Odometer: 2577 km

Engine Capacity: 1991 cc

Market Value/New Car Price: S\$280,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 245/40 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,896.16	11,750.50	1,145.66	8.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,520.00	12,920.00	2,600.00	16.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,416.16	24,670.50	3,745.66	13.18
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	27,716.16	23,970.50	3,745.66	13.51
+ GST 8.00/8.00% (S\$)	2,217.29	1,917.64	299.65	13.51
Nett Amount (S\$)	29,933.45	25,888.14	4,045.31	13.51

INSPECTION

Date of Assignment: 16/01/2023

Date Inspected: 17/01/2023 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 11.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2023)
Parts:	M1-COUPE	MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGA3030E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN HUPER OPTIK SOLAR FILM	Necessary	300.00 FS	*300.00 FS
2	1		*RH/REAR DOOR	Bent	2,946.63 FS	*2,946.63 FS
3	1		*RH/REAR DOOR SEAL	Necessary	317.72 FS	*317.72 FS
4	1		*RH/REAR DOOR INSULATION	Necessary	44.29 FS	*44.29 FS
5	2		*RH/REAR DOOR DOWEL	Necessary	8.80 FS	*8.80 FS
6	1		*RH/REAR FENDER	Bent	2,648.20 FS	*2,648.20 FS
7	1		*TANK FILLER RECESS	Not Necessary	237.80 FS	*- FS
8	1		*INTERMEDIATE LAYER	Necessary	5.12 FS	*5.12 FS
9	1		*REAR WINDOW	Necessary	1,566.23 FS	*1,566.23 FS
10	1		*WINDOW ANTENNA	Necessary	145.80 FS	*145.80 FS
11	2		*ONE-COMPONENT ADHESIVE	Necessary	367.62 FS	*367.62 FS
12	1		*RH/REAR DISK WHEEL	Scratched	966.89 FS	*966.89 FS
13	1		*REAR BUMPER	Scratched	987.75 FS	*987.75 FS
14	12		*RIVET FOR BUMPER	Necessary	64.08 FS	*64.08 FS
15	1		*RH/RUNNING BOARD	Repair	907.86 FS	*- FS
16	1		*WHITE SEAM SEALING COMPOUND	Necessary	116.42 FS	*116.42 FS
17	20		*BLIND RIVET 6.4 X 12	Necessary	34.00 FS	*34.00 FS
18	3		*BLIND RIVET W CSK. HEAD 6.4 X 14.0	Necessary	6.03 FS	*6.03 FS
19	1		*TS TWO-COMPONENT ADHESIVE	Necessary	904.72 FS	*904.72 FS
20	1		*TWO-COMPONENT ADHESIVE	Necessary	118.43 FS	*118.43 FS
21	1		*CAVITY PRESERVATIVE	Necessary	116.39 FS	*116.39 FS
22	1		*ZINC DUST PAINT	Necessary	66.41 FS	*66.41 FS
23	1		*DAMPING, SIDE WALL	Necessary	18.97 FS	*18.97 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **12,896.16** **11,750.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH	New	6,720.00	4,800.00
2	RESPRAY RH/FRONT DOOR & RH/REAR DOOR & RH/REAR FENDER & REAR BUMPER RH/RUNNING BOARD & END PANEL	New	4,200.00	4,000.00
3	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
4	REPLACE RIGHT REAR DOOR, TRANSFER COMPONENT PARTS	New	480.00	480.00
5	REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR	New	480.00	480.00
6	REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UPHOLSTERY ETC FOR NECESSARY REPAIR	New	1,440.00	960.00
7	TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS IF NECESSARY	New	240.00	240.00
8	TO INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
9	LABOUR TO REMOVE AND INSTALL TYRE FROM RIM. (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD	New	60.00	60.00
10	REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL	New	560.00	560.00
11	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM	New	180.00	180.00
12	BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS / COMPONENTS	New	120.00	120.00
13	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
Gross Labour Cost (S\$)			15,520.00	12,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >