

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9836E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WINDSCREEN (WCP)	CRACKED	450.00	450.00
1	FRONT WINDSCREEN RUBBER (WCP)	NECESSARY	95.00	95.00
1	FRONT WIPER PANEL (WCP)	BENT	130.00	130.00
1	FRONT BODY PANEL (WCP)	BENT	450.00	450.00
1	FRONT RADIATOR GRILLE (WCP)	CRACKED	195.00	195.00
1	GRILLE LOGO EMBLEM (WCP)	NECESSARY	35.00	35.00
1	FRONT BUMPER (WCP)	CRACKED	220.00	220.00
1	FRONT BUMPER BRACKET LH (WCP)	BENT	100.00	100.00
1	FRONT BUMPER BRACKET RH (WCP)	BENT	100.00	100.00
1	FRONT HEADLAMP LH (WCP)	CRACKED	300.00	300.00
1	FRONT HEADLAMP RH (WCP)	CRACKED	300.00	300.00
1	DYNA EMBLEM (WCP)	NECESSARY	25.00	25.00
1	FRONT BRAKE VACUUM SWITCH (ADDITIONAL) (WCP)	CRACKED	50.00	50.00
1	FRONT FOG LAMP COVER RH (ADDITIONAL) (WCP)	DENTED	30.00	30.00
6	RADIATOR CLIPS @\$3.50 (ADDITIONAL) (WCP)	NECESSARY	21.00	21.00
1	FRONT PANEL CLIP (ADDITIONAL) (WCP)	NECESSARY	3.00	3.00
	COST PLUS 10%		250.40	250.40
			2,754.40	2,754.40
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	25.00	25.00
			25.00	25.00
	<u>LABOUR</u>			
	TO STRAIGHTEN FRONT BODY INCLUDING CUTTING, WELDING + RENEW OF PARTS.		400.00	400.00
	TO RESPRAY PAINT FRONT FENDER LH + RH.		900.00	800.00
	TO DISMANTLE + RENEW FRONT WINDSCREEN.		120.00	60.00
	TO DISMANTLE + REFIX FRONT DASHBOARD.		300.00	250.00
			1,720.00	1,510.00
	GRAND TOTAL		4,499.40	4,289.40

Report Ref No. CS/UOI23000481/Kqy3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		4,289.40
LESS EXCESS		-1,500.00
NETT LIABILITY		2,789.40

Report Ref No. CS/UOI23000481/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser