

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 4338B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED / DENTED	581.40	581.40
1	FRONT GRILLE	SERVICEABLE	443.00	-
10	CLIP @\$4.80	NECESSARY	48.00	48.00
	LESS 25% DISCOUNT		-268.10	-157.35
			804.30	472.05
	<u>LABOUR</u>			
	TO REPLACE GRILLE & BUMPER.		200.00	200.00
	TO SPRAY PAINTS ON SAME.		400.00	220.00
			600.00	420.00
	GRAND TOTAL		1,404.30	892.05

RECOMMENDED COST OF LUMP SUM REPAIRS		700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/LIP23000485/Kvy3m4

MARKET VALUE: \$125,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$46,733.00=NETT VALUE: \$78,267.00

KONG SENG CHEONG

Licensed Appraiser