

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23000490/UVY3E2**Date:** 15/02/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001491115
Claimant Vehicle No :	SMZ8139R	Insured Vehicle No :	SFV9966S
Date of Loss:	13/01/2023	Nature of Claim:	TP
		Claim No:	299643

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ8139R	Engine No:	2AR1027954
Make & Model:	LEXUS ES300H, 2.5 Luxury (A)	Chassis No:	JTHBW1GG002052991
Reg. Date:	03/03/2014 (Man. Year: 2014)	Odometer:	163714 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,559.02	1,793.43	4,765.59	72.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	510.00	1,430.00	73.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,499.02	2,303.43	6,195.59	72.90
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	8,499.02	1,800.00	6,699.02	78.82
+ GST 8.00/8.00% (S\$)	679.92	144.00	535.92	78.82
Nett Amount (S\$)	9,178.94	1,944.00	7,234.94	78.82

INSPECTION

Date of Assignment:	16/01/2023	
Date Inspected:	16/01/2023	Inspected At: Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Feb 2023)
Parts:	143	LEXUS ES300H 2.5 Luxury (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ8139R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,345.00 FN	*1,345.00 FN
2	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	180.20 FN	*- FN
3	1		*SET FRONT BUMPER CLIP	Necessary	65.00 FN	*65.00 FN
4	1		*FRONT FOG LAMP RH	Not Necessary	381.90 FN	*- FN
5	1		*FRONT FOG LAMP, CHROME CORNER RH	Not Necessary	141.50 FN	*- FN
6	1		*FRONT PDC SENSORS RH	Damaged	380.00 FN	*361.00 FN
7	1		*FRONT NOSERING (RH)	Cracked	221.70 FN	*221.70 FN
8	1		*FRONT NOSERING COVER (RH)	Not Necessary	74.80 FN	*- FN
9	1		*FRONT HEADLAMP	Not Necessary	3,929.10 FN	*- FN
10	1		*FRONT HEADLAMP LOWER	Not Necessary	105.00 FN	*- FN
11	1		*FRONT WIPPER TANK	Not Necessary	281.60 FN	*- FN
12	1		*FRONT BUMPER SPONGE	Not Necessary	182.00 FN	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	7,287.80	1,992.70
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	728.78	199.27
Total Parts (\$\$)	6,559.02	1,793.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	200.00
2	TO RESPRAY PAINTING ON AFFECTED AREAS	New	800.00	250.00
3	TO APPLY UNDERCOATING	New	120.00	0.00
4	TO REMOVE AND REFIT FRONT REVERSE SENSOR	New	100.00	40.00
5	TO REMOVE, REPLACE DAMAGED LAMP AND CHECK FRONT WIRING	New	120.00	20.00
Gross Labour Cost (\$\$)			1,940.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >