1/19/23, 2:38 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI23000515/KVP3E2

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 Date: 19/01/2023

REFERENCE

Insured/Claimant: Toh Mun Wah Policy No: DMPCSNW00237902202

Date of Loss: 07/01/2023 Nature of Claim: OD Claim No: SNM23D200195/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS3739A

Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A) Engine No: CZC144472

Reg. Date: 17/11/2016 (Man. Year: 2016) Chassis No: WVWZZZAUZHW073457

Colour: Metallic Blue Odometer: 53492 km

Engine Capacity: 1395 cc
Market Value/New Car

Price: S\$56,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		60.00	0.00	60.00	100.00
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	60.00	0.00	60.00	100.00
	- Excess (S\$)	0.00	500.00	-500.00	
	(S\$)	60.00	-500.00	560.00	933.33
	+ GST 8.00/0.00% (S\$)	4.80	0.00	4.80	100.00
	Nett Amount (S\$)	64.80	-500.00	564.80	871.60

INSPECTION

Date of Assignment: 13/01/2023 Present Location: S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 16/01/2023 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$56,000.00 OMV : \$23,827.00 PARF Rebate (1): \$9,982.00 \$52,668.00 Quota Premium Paid: COE Rebate (2): \$20,189.00 Total Rebate (1) + (2) = : \$30,171.00

The total amount incurred will be Market Value \$56,000.00 minus Total Rebate \$30,171.00 = \$25,829.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2023)

Parts: 144 VOLKSWAGEN GOLF 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGS3739A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars	Repairer's	Amount
Miscellaneous Items		
1 1 Towing	60.00	0.00
Sub Total (S\$)	60.00	0.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >