

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000519/SVP3Q2**Date:** 31/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00140552200
Claimant Vehicle No :	YQ4978S	Insured Vehicle No :	XD9479M
Date of Loss:	21/12/2022	Nature of Claim:	TP
		Claim No:	SNM23D200388/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ4978S	Engine No:	N04CWN16291
Make & Model:	HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M)	Chassis No:	JHHUCV3F40K041223
Reg. Date:	19/11/2021 (Man. Year: 2021)	Odometer:	28828 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,405.00	3,215.00	9,190.00	74.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	600.00	4,800.00	88.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,805.00	3,815.00	13,990.00	78.57
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	17,805.00	3,050.00	14,755.00	82.87
+ GST 8.00/8.00% (S\$)	1,424.40	244.00	1,180.40	82.87
Nett Amount (S\$)	19,229.40	3,294.00	15,935.40	82.87

INSPECTION

Date of Assignment:	16/01/2023	
Date Inspected:	17/03/2023 Inspected At:	56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775 Repairer:AP Automotive Services Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 May 2023)	
Parts:	N/A	HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ4978S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR CHASSIS SAFETY BAR (WOODEN)	Not Necessary	375.00 F	*- F
2	1		*REAR BUMPER	Not Necessary	1,275.00 F	*- F
3	1		*REAR NUMBER PLATE LAMP	Not Necessary	90.00 F	*- F
4	1		*REAR NUMBER PLATE LAMP BRACKET	Not Necessary	180.00 F	*- F
5	2		*TAIL LAMP	Not Necessary	720.00 F	*- F
6	2		*REAR BOX OPEN DOOR	Dented	3,600.00 FS	*2,200.00 FS
7	2		*REAR BOX OPEN DOOR HINGE	Not Necessary	360.00 FS	*- FS
8	2		*REAR BOX OPEN DOOR LOCK BAR	Not Necessary	2,550.00 FS	*- FS
9	2		*REAR BOX OPEN DOOR LOCK BAR BRACKET	Not Necessary	450.00 FS	*- FS
10	2		*REAR BOX OPEN DOOR STAY	Not Necessary	75.00 FS	*- FS
11	1		*REAR BOX OPEN DOOR DECAL STICKER	Necessary	2,700.00 FS	*1,000.00 FS
12	1		*REAR BOX OPEN DOOR 60KM/H STICKER	Necessary	30.00 FS	*15.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					12,405.00	3,215.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	400.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	200.00
3	TO CHECK WATER LEAK	New	200.00	0.00
4	TO APPLY RUST PROOFING	New	300.00	0.00
5	WIRING CHECK	New	300.00	0.00
6	REAR CHASSIS ALIGNMENT	New	800.00	0.00
Gross Labour Cost (S\$)			5,400.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >