



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 3692C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR SIDE MIRROR RH	DAMAGED	1,450.00	981.00
1	FRONT DOOR RH	NOT NECESSARY	1,510.00	-
1	FRONT DOOR LOWER GUARD RH	NOT NECESSARY	210.00	-
1	FRONT DOOR OUTER STRIP RH	NOT NECESSARY	195.00	-
1	SET FRONT DOOR STICKER RH (BLACK)	NOT NECESSARY	190.00	-
	LESS 25% DISCOUNT		-888.75	-245.25
			2,666.25	735.75
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT DOOR LOWER GUARD RH CLIP (SN)	NOT NECESSARY	40.00	-
			40.00	-
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		400.00	100.00
	TO SPRAY PAINT AFFECTED AREA.		400.00	100.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	WIRING CHECK.	NOT NECESSARY	100.00	-
	TRANSFER FRONT DOOR MECHANISM.	NOT NECESSARY	80.00	-
			1,130.00	200.00
	GRAND TOTAL		3,836.25	935.75

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			750.00
---	--	--	---------------

Report Ref No. CS/FCI23000528/Any3m4

MARKET VALUE: \$57,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$37,9750.00=NETT VALUE: \$19,025.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.