

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000534/UVP3Q2**Date:** 09/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00216102200
Claimant Vehicle No :	SLL9488L	Insured Vehicle No :	SMQ7220S
Date of Loss:	15/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200390/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL9488L	Engine No:	G4FMMU040144
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHLN41ETNU206079
Reg. Date:	14/10/2021 (Man. Year: 2021)	Odometer:	43857 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,703.00	3,418.16	6,284.84	64.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,250.00	970.00	43.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,923.00	4,668.16	7,254.84	60.85
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	11,923.00	3,700.00	8,223.00	68.97

INSPECTION

Date of Assignment:	17/01/2023	
Date Inspected:	17/01/2023 Inspected At:	Huat Hock Motor Workshop (HQ) BLK 3012 BEDOK NORTH AVE 4, #01-2054 BEDOK INDUSTRIAL PARK E Singapore 1648
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2023)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL9488L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Badly Dented	2,148.10 F	*1,993.00 FL
2	1		*FRONT DOOR HINGE RH (UPPER)	Not Necessary	56.30 F	*- FL
3	1		*FRONT DOOR HINGE RH (LOWER)	Not Necessary	44.20 F	*- FL
4	1		*FRONT DOOR CHECK RH	Not Necessary	75.20 F	*- FL
5	1		*FRONT DOOR RH TRIM BOARD	Not Necessary	829.40 F	*- FL
6	1		*FRONT DOOR RH WEATHERSTRIP (INNER)	Necessary	115.30 F	*115.30 FL
7	1		*FRONT DOOR RH WEATHERSTRIP (OUTER)	Not Necessary	126.10 F	*- FL
8	1		*REAR DOOR RH	Badly Dented	2,145.20 F	*1,995.00 FL
9	1		*REAR DOOR HINGE RH (UPPER)	Not Necessary	56.30 F	*- FL
10	1		*REAR DOOR HINGE RH (LOWER)	Bent	44.20 F	*44.20 FL
11	1		*REAR DOOR CHECK RH	Not Necessary	75.20 F	*- FL
12	1		*REAR DOOR RH TRIM BOARD	Not Necessary	825.90 F	*- FL
13	1		*REAR DOOR RH WEATHERSTRIP	Necessary	125.20 F	*125.20 FL
14	1		*RH CENTRE DOOR PILLAR	Repair	1,245.90 F	*- FL
15	1		*FRONT DOOR RH HANDLE (OUTER)	Not Necessary	89.20 F	*- FL
16	1		*FRONT DOOR RH LOCK ASSEMBLY	Not Necessary	381.20 F	*- FL
17	1		*REAR DOOR RH LOCK ASSEMBLY	Not Necessary	381.20 F	*- FL
18	1		*FRONT DOOR RH WINDOW GLASS	Not Necessary	147.30 F	*- FL
19	1		*FRONT DOOR RH WINDOW GLASS REGULATOR	Not Necessary	223.40 F	*- FL
20	1		*FRONT DOOR RH POWER WINDOW SWITCH	Not Necessary	128.20 F	*- FL
21	1		*SET REAR DOOR TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
22	1		*RH REAR DOOR ELECTRICAL WIRE HARNESS	Not Necessary	180.00 FS	*- FS
23	1		*SET FRONT DOOR TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
24	1		*RH FRONT DOOR ELECTRICAL WIRE HARNESS	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,703.00	4,272.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	854.54
Total Parts (\$\$)	9,703.00	3,418.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ANTI-RUST TREATMENT	New	120.00	60.00
2	REWIRING TO FACILITATE WORKS	New	120.00	20.00
3	TRANSFER OF FRONT AND REAR DOOR MECHANISM	New	280.00	120.00
4	LABOUR TO REMOVE AND REPLACE DAMAGED PARTS (INCLUDING REFITTING AND REPOSITIONING OF REPLACED PARTS)	New	800.00	450.00
5	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK	New	900.00	600.00
Gross Labour Cost (S\$)			2,220.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >